

FEDERAL RADIOLOGICAL

MONITORING AND ASSESSMENT CENTER

FRMAC FLY AWAY LABORATORY MANUAL




The Federal Manual for Performing Laboratory Analysis
during a Radiological Emergency

October, 2019


Prepared by
Sandia National Laboratories
Albuquerque, New Mexico 87185 and Livermore, California 94550
Sandia National Laboratories is a multimission laboratory managed and operated by National Technology & Engineering Solutions of Sandia, LLC, a wholly owned subsidiary of Honeywell International Inc., for the U.S. Department of Energy's National Nuclear Security Administration under contract DE-NA0003525.

FRMAC Fly Away Laboratory Manual



10/7/19

Elliott J. Leonard
FRMAC Laboratory Analysis FAL Supervisor
Sandia National Laboratories
Albuquerque, NM



Phil Torretto
FRMAC Laboratory Analysis Working Group
Lawrence Livermore National Laboratory
Livermore, CA



10/8/19

Arthur Shanks Jr., Technical Chairman
FRMAC Laboratory Analysis Working Group
Sandia National Laboratories
Albuquerque, NM

This work was supported by the U.S. Department of Energy, National Nuclear Security Administration Nevada Operations Office, under Contract No. DE-AC08-96NV11718.

FRMAC is an acronym for Federal Radiological Monitoring and Assessment Center.

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, nor any of their contractors, subcontractors or their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or any third party's use or the results of such use of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof or its contractors or subcontractors. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

AVAILABILITY

Available for sale to the public, in paper, from:

U.S. Department of Commerce
National Technical Information Service
5285 Port Royal Road
Springfield, VA 22161
phone: 800.553.6847
fax: 703.605.6900
email: orders@ntis.gov
online ordering: <http://www.ntis.gov/ordering.htm>

Available electronically at <http://www.osti.gov/bridge>

Available for a processing fee to U.S. Department of Energy
and its contractors, in paper, from:

U.S. Department of Energy
Office of Scientific and Technical Information
P.O. Box 62
Oak Ridge, TN 37831-0062
phone: 865.576.8401
fax: 865.576.5728
email: reports@adonis.osti.gov

Also available at the FRMAC website,

https://www.nnss.gov/pages/programs/FRMAC/FRMAC_DocumentsManuals.html

Preface

This manual was written for those personnel who respond to a radiological/nuclear incident that will be called upon to provide proper analysis support. Overall, this manual provides general guidance and some specific diagrams and forms. However, it is understood that site- and event-specific operational decisions and procedures may need to be modified at the time of an emergency event. This manual is intended to provide guidance for Fly Away Laboratory personnel without limiting FRMAC's ability to integrate the work with other partners or stakeholders.

The NNSA/NSO has the overall responsibility for maintaining the master copy of all FRMAC manuals. Please provide comments on this manual to:

U.S. Department of Energy
National Nuclear Security Administration
Nevada Site Office
Attn: FRMAC Program Manager
P.O. Box 98518
Las Vegas, Nevada 89193-8518

Acknowledgments

Creation of the *FRMAC Fly Away Laboratory (FAL) Manual* was a major undertaking to which many people contributed. Special thanks go to Elliott Leonard Sean Fournier and Ken Sansone of Sandia National Laboratories; Manuel Franco Jr. and Luis Valdivia of Apple One; Wendy Pemberton of the Remote Sensing Laboratory; and Richard Bibby, Cynthia Conrado, Jay Dixon, Mark Johnson and Phil Torretto of Lawrence Livermore National Laboratory who developed and organized much of the material in this revision.

Acronyms and Abbreviations

ADC	Analog to Digital Converter
ALARA	As Low As Reasonably Achievable
ARF	Analysis Request Form
ARMS	Asset Readiness Management System
CM	Consequence Management
CMHT	Consequence Management Home Team
CMRT I	Consequence Management Response Team phase I
DOE	Department of Energy
DQO	Data Quality Objectives
EOTA	Emergency Operations Training Academy
FAL	Fly Away Laboratory
FRMAC	Federal Radiological Management Assessment Center
FWHM	Full Width at Half Maximum
GAB	Gross Alpha/Beta
HPGe	High Purity Germanium
HVPS	High Voltage Power Supply
ICS	Incident Command System
LAN	Local Area Network
LLD	Lower Level Discriminator
LSC	Liquid Scintillation Counting
MCA	Multi-Channel Analyzer
MQO	Measurement Quality Objectives
NIST	National Institute of Standards and Technology
NNSA	National Nuclear Security Administration
NSO	Nevada Site Office
QA	Quality Assurance
QC	Quality Control
RSL	Remote Sensing Laboratory
SCF	Sample Control Form
SNL	Sandia National Laboratories
SOP	Standard Operating Procedure
USB	Universal Serial Bus

Table of Contents

Revision Date

Section 1. Introduction.....	1-1	11/13
Section 2. Roles and Responsibilities.....	2-1	11/13
Section 3. Quality Control.....	3-1	8/19
Section 4. Sample Control.....	4-1	8/19
Section 5. Logistics.....	5-1	11/13
Section 6. Gamma Spectroscopy Procedures.....	6-1	8/19
Section 7. iSOLO™ Operations.....	7-1	8/19
Section 8. Analytical Balance Use.....	8-1	11/13
Section 9. Data Handling and Verification/Validation.....	9-1	11/13

List of Appendices

Appendix A: iSOCS™ Geometry Composer Tutorial.....	A-1	11/13
Appendix B: Fly Away Laboratory Forms.....	B-1	8/19

This page is intentionally left blank

Section 1: Introduction

When the FRMAC responds to a radiological/nuclear incident, monitoring, sampling, and radioanalytical support will arrive from several different sources. The responders providing this support will, likely, have received varying levels of training and will have experience with a variety of monitoring, sampling, and radioanalytical equipment and procedures. It is important that an acceptable and established set of standard operating procedures (SOPs) be followed by all personnel having responsibilities for processing and analyzing samples during the emergency. Overall, this manual provides general guidance and some specific diagrams and forms. However, it is understood that site- and event-specific operational decisions and procedure parameters will need to be established and documented at the time of an emergency.

The purpose of this manual is to provide guidance to Fly Away Laboratory (FAL) personnel responsible for the analysis of time sensitive radiological samples. With proper training, preparation, and equipment, FAL personnel will be able to quickly provide reliable results for radiological samples that have been deemed immediately important to the health and safety of emergency response personnel as well as the general public. Upon deployment of the FRMAC, the Consequence Management Response Team will have set up shelter and workspace for the FAL. Equipment load-outs have been designed to be able to be shipped via commercial airlines or DOE aircraft. In this way, the FAL will most likely be the first field laboratory on-site and will be crucial in the rapid analysis of emergency-phase samples.

It is the responsibility of CMRT personnel to deploy the laboratory specific-equipment and begin operations upon arrival. This manual will provide guidance as to how to set up an efficient laboratory working area. However, it will be up to the FAL personnel to be able to adapt to any situation that may come up during an event. Although a part of the FRMAC, the FAL will be acting as a laboratory entity with respect to the other FRMAC functions (Laboratory Analysis, Assessment, Monitoring and Sampling, Health and Safety) and will take direct instruction from the FAL Manager and FRMAC Laboratory Analysis personnel.

Work in the Fly Away Laboratory may require working outdoors in possibly extreme conditions. Watch for snakes, rodents, insects, and other potentially hazardous flora or fauna. Be aware of changing weather conditions, and immediately follow all orders regarding the protection of your health and safety.

This page is intentionally left blank

Section 2: Roles and Responsibilities

Table of Contents

2.1	Position Descriptions	2
2.1.1	Fly Away Laboratory Manager	2
2.1.2	Fly Away Laboratory Analst.....	3
2.2	Required Training Matrix	5

Tables

Table 2.1:	FAL Personnel Training Requirements	5
------------	---	---

2.1 Position Descriptions

2.1.1 Fly Away Laboratory Manager

The FRMAC Fly Away Laboratory (FAL) Manager maintains close coordination with the FRMAC Laboratory Analysis Manager. The FAL Manager communicates and interfaces with FAL personnel to ensure that the FAL's resources are adequately and correctly used.

Deploys in Phase I – No

Deploys in Phase II - Yes

2.1.1.1 Duties and Responsibilities

- Maintain a general working knowledge and understanding of FRMAC missions, capabilities, objectives, and procedures
- Maintain expert working knowledge and experience in radiochemical analytical methods, laboratory operations, laboratory QA/QC, and environmental radiochemistry
- Maintain detailed knowledge, expertise, and proficiency with the *FRMAC Fly Away Laboratory Manual*, laboratory sample tracking, and data analysis software
- Communicate sample priorities from the Laboratory Analysis Group to the FAL Staff
- Communicate analytical capability and capacity of the FAL to the FRMAC Laboratory Analysis Manager and FRMAC Laboratory Analysis Deputy Manager
- Participate in calls, meetings, and conferences of the Laboratory Analysis Working group during an active event
- Act as the final approval in the quality assurance data review process for all samples analyzed by the FAL

2.1.1.2 Organization and Communications

- RECEIVES DIRECTION FROM:
 - FRMAC Laboratory Analysis Manager
- WORKS WITH:
 - FRMAC Laboratory Analysis Manager
 - FRMAC Deputy Laboratory Analysis Manager
 - FRMAC Laboratory Analysis Personnel
 - FAL Laboratory Staff
- PROVIDES DIRECTION TO:
 - FAL Laboratory Staff

2.1.1.3 Skills and Knowledge

- Maintain a general working knowledge and understanding of FRMAC missions, capabilities, objectives, and procedures
- Maintain expert working knowledge and experience in radioanalytical methods, laboratory operations, laboratory QA/QC, and environmental radiochemistry

- Demonstrated extensive knowledge and experience in laboratory and environmental radiochemistry methods
- Working knowledge and experience with DQOs, analytical methods, minimum detectable activity (MDA) calculations, and quality assurance procedures
- Working knowledge and experience with DRLs, AALs, EPA PAGs and FDA intervention levels
- Radiation Worker I trained
- Successful completion of all training identified in Asset Readiness and Management System (ARMS)
- Authorized for deployment

2.1.1.4 Education and Experience

- Active participation in an official FRMAC exercise as part of the FAL team
- Minimum of 3 years of experience managing a radioanalytical laboratory and managing radioanalytical analyses

2.1.1.5 Physical Demands and Requirements

- Able to adapt and work in austere living conditions
- Able to work long hours in possibly stressful, urgent situations
- Able to adapt and work in extreme temperature and weather conditions

2.1.2 Fly Away Laboratory Analyst

The FRMAC Fly Away Laboratory (FAL) Analyst is responsible for receiving, inspecting, and logging in samples that have been submitted to, and screened by Health and Safety personnel. The FAL Analyst place samples in the staging area and assists in preparing these samples for analysis by completing the necessary documentation. Once documentation is complete, the FAL Analyst places the samples into proper storage. The FAL Analysts are required to perform requested analyses on samples received. This task includes sample preparation, detector setup, sample counting, data analysis, and review.

Deploys in Phase I – No

Deploys in Phase II - Yes

2.1.2.1 Duties and Responsibilities

- Maintain a general working knowledge and understanding of FRMAC missions, capabilities, objectives, and procedures
- Maintain detailed knowledge and familiarity with the *FRMAC Fly Away Laboratory Manual* and sample control and data analysis software
- Review, validate, and sign chain of custody documentation (Analysis Request Forms).
- Log samples into the FAL sample tracking system
- Record sample tracking information and prepare necessary paperwork
- Remain cognizant of contamination control procedures during all sample control and handling activities

- Perform sample preparation
- Perform Gamma spectral analysis and detector efficiency modeling using vendor software
- Perform liquid scintillation analysis
- Perform gross alpha/beta analysis
- Perform data report generation using custom software developed for the FAL
- Review laboratory results for errors
- Maintain instrumentation in working condition and calibration
- Perform routine quality control schedules for each instrument
- Troubleshoot hardware and software issues relevant to radiation detection instrumentation

2.1.2.2 Organization and Communications

- RECEIVES DIRECTION FROM:
 - FRMAC FAL Manager
- WORKS WITH:
 - FRMAC Laboratory Analysis Personnel
 - FRMAC FAL Manager
- PROVIDES DIRECTION TO:
 - N/A

2.1.2.3 Skills and Knowledge

- Maintain a general working knowledge and understanding of FRMAC missions, capabilities, objectives, and procedures
- Maintain working knowledge and experience in radioanalytical methods, laboratory operations, laboratory QA/QC, and environmental radiochemistry.
- Demonstrated knowledge and experience in laboratory and environmental radiochemistry
- Radiation Worker I trained
- Successful completion of all training identified in Asset Readiness and Management System (ARMS)
- Authorized for deployment

2.1.2.4 EDUCATION AND EXPERIENCE

- Active participation in an official FRMAC exercise as part of the FAL team
- Minimum of 1 year experience performing analyses using Gamma Spectroscopy, Alpha/Beta counting, or Liquid Scintillation counting, or has completed all of the required training and works with a more experienced FAL Analyst

2.1.2.5 PHYSICAL DEMANDS AND REQUIREMENTS

- Able to adapt and work in austere living conditions
- Able to work long hours in possibly stressful, urgent situations
- Able to adapt and work in extreme temperature and weather conditions

2.2 Required Training Matrix

Table 2.1: FAL Personnel Training Requirements

Description	Frequency	Fly Away Lab Manager	Laboratory Staff
ICS 100- Introduction to ICS	1 time	X	X
ICS-200 – ICS for Single resources and Initial Action Incidents	1 time	X	X
ICS-800.b National Response Framework (NRF)Introduction.	1 time	X	X
DOE Rad Worker II (or equivalent)	Current	X	X
FAL -100 – FAL Field Logistics	3 yrs	X	X
FAL-200 – FAL Gamma Spectroscopy Operations	3 yrs	X	X
FAL-300 – FAL Gross Alpha/Beta Operations	3 yrs	X	X
FAL-600 – FAL Gamma Spectrometer Maintenance	3 yrs	X	
FAL-700- FAL Gross Alpha/Beta Routine Maintenance	3 yrs	X	

This page is intentionally left blank

Section 3: Quality Control

Table of Contents

3.1	Introduction	2
3.2	QC Sample Assignment and Preparation	2
3.3	QC Sample Processing.....	2
3.3.1	Quality Control Samples.....	2
3.3.2	Blank Samples	2
3.3.3	Laboratory Control Samples (LCS).....	3

3.1 Introduction

The purpose of processing quality control (QC) samples is to provide continuing assurance of laboratory performance and to make internal laboratory performance audits more effective. Positive controls (laboratory control sample [LCS], blind quality control sample [BQC], and matrix spike samples) serve as a monitor of the overall accuracy of all steps in the analysis, including sample preparation. Negative controls (matrix blanks, backgrounds, and reagent blanks) are used to assess the existence and magnitude of contamination problems as well as natural background contributions. If problems with any QC sample exist, all data associated with the batch shall be carefully evaluated to determine whether the sample results are adversely affected.

Acceptance limits are predetermined and set in the software for each piece of instrumentation. These values are set to typical acceptance limits for laboratory-grade instrumentation. However, due to the variability in the environment, the Fly Away Laboratory Manager has the authority to alter acceptance limits based on the situation.

3.2 QC Sample Assignment and Preparation

At a minimum, a set of QC samples should consist of one positive control and one negative control. Assign a set of QC samples to each preparation batch of samples. The minimum number of QC samples shall be one set included in each batch, where the batch does not exceed a total of 20 samples. If reasonable, positive controls should have activity concentrations appropriate for the required measurement quality objectives (MQOs). Typically, LCS, BQCs, and/or matrix spike sample concentrations should be at least 10 times the required critical level (L_c) if possible.

3.3 QC Sample Processing

3.3.1 Quality Control Samples

QC samples serve as indicators of method performance. If the QC results fall outside of the acceptance limits, all data associated with the batch shall be carefully evaluated to determine if the samples were compromised, and appropriate corrective actions shall be taken. Reprocess any samples that are suspected to be compromised. If reprocessing is not possible, contact the FAL Manager. Reprocesses are documented in the case file associated with the group for samples in question. Suspect results are qualified on the customer report. Instrument QC checks should be performed routinely to ensure the instrument has not been contaminated and is operating within control. Appropriate corrective actions (adjustments to the instrumentation, decontamination, and/or recalibration) shall be performed if an instrument is determined to be operating outside of tolerance limits. Record any corrective actions in the instrument's logbook.

3.3.2 Blank Samples

Blank analysis results are assessed to determine the existence and magnitude of contamination problems. The criteria for evaluation of blanks apply to any blank associated with the samples. Review the results of the blanks. If the blank results fall outside the appropriate tolerance limits, all data associated with the batch shall be carefully evaluated to determine whether the samples were contaminated. Reprocess any samples that are suspected to be contaminated. If

reprocessing is not possible, contact the FAL Manager. Document reprocesses in the batch file associated with the group of samples in question. Qualify suspect results are on the customer report.

3.3.3 Laboratory Control Samples (LCS)

The LCS serves as a monitor of the overall accuracy and performance of all steps in the analysis, including the sample preparation. The LCS should contain an activity greater than 10 times the radionuclide's critical level, if possible. All LCS results should fall within the pre-established tolerance limits, if applicable. If the LCS recoveries fall outside the appropriate tolerance limits, all data associated with the batch shall be carefully evaluated to determine whether the actual sample results were affected, and appropriate corrective actions shall be taken. Reprocess any samples that are suspected to be affected. If reprocessing is not possible, contact the FAL Manager.

This page is intentionally left blank

Section 4: Sample Control

Table of Contents

4.1	Introduction	2
4.2	Setup of the Sample Control Staging Area	2
4.3	Sample Login and Tracking Process	3
4.3.1	Samples for Routine Analysis	3

Figures

Figure 4.1:	Example - Sample Control Staging Area Recommended Setup	3
Figure 4.2:	Tracking Database Main Menu	4

4.1 Introduction

Upon deployment of the FRMAC Fly Away Laboratory, CMRT personnel will have deployed the materials for an appropriate staging area. This section of the manual outlines the recommended setup of the sample control area, where samples that are collected in the field will be brought and logged into the FAL system. This section also outlines the logistical requirements of the sample tracking process.

Sample tracking can be handled with the FAL Login excel spreadsheet. At the start of an event, open the **FAL LOGIN TEMPLATE.XLTM** located on the sample login computer, or on the shire FAL SharePoint. Fill out the header section Event Name and Start Date. Save the with the filename that matches the event name.

4.2 Setup of the Sample Control Staging Area

There likely will be adequate tables and chairs to establish a sample control staging area onsite. This area includes designated areas for temporary storage of samples received, a computer login station, and areas for samples that require analysis, organized by the type of analysis requested . The designated storage areas are marked off with tape and labeled with a marker.

Refer to Figure 4.1 for an example of the staging area layout.




Figure 4.1: Example - Sample Control Staging Area Recommended Setup

It is recommended to set up the sample control staging area in such a way that it is clear which samples have been logged into the system and are ready for analysis. All samples must be processed through such a staging area before entering the laboratory area. When samples contain significant quantities of radioactive material, be sure to align any staging or storage areas to keep the dose to FAL personnel as low as reasonably achievable (ALARA) and ensure that the instrument backgrounds are not affected by the flux of samples in and out of the storage area. The use of temporary shielding or out-of-the-way storage areas may be required. Temporary shield can be constructed using empty equipment boxes or coolers filled with water. You may choose to request a radiological survey to be performed in this staging area by FRMAC Health and Safety Radiological Control Technicians to be sure. You may also want to rerun backgrounds on the FAL instrumentation when radiological conditions change in the storage/staging area.

4.3 Sample Login and Tracking Process

4.3.1 Samples for Routine Analysis

Routinely, samples are brought by FRMAC Laboratory Analysis personnel to the Fly Away Laboratory sample control staging area. Each group of samples has an Analysis Request Form (ARF). This ARF includes all the required information to perform the analysis of the sample(s). Each sample in a batch has a unique number associated with it, known as a “Sample Control Form (SCF) or Sample number.” Upon receipt of a batch of samples, FAL Staff complete the following:

1. The samples have been screened for external removable contamination at the hotline by a FRMAC Radiation Control Technologist (RTC). If a breach in the contaminant is suspected immediately contact FRMAC Health and Safety for a contamination screening and keep everyone in the area to avoid the spread of contamination.
- 3.
2. Confirm that all the samples listed on the ARF are included in the shipment to the staging area.
- 4.
3. Have the courier of the samples sign the chain-of-custody line on the ARF indicating that the samples are now leaving their possession.
- 5.
4. Sign the chain-of-custody line on the ARF indicating that you (FRMAC Fly Away Laboratory) are now in custody of the samples. If the sample is contaminated, contact the FAL Manager for guidance.
- 6.
5. Place the samples in the designated drop-off point.
- 7.

- Log the sample into the FAL login excel sheet created for the current event, as in Figure 4.2.




Figure 4.2: Tracking Database Main Menu

- Enter the sample information by filling out the form:
 - SCF number in the first column (A),
 - ARF number in the second column (B),
 - requested Analysis in the third column (C),
 - sample matrix in the fourth column (D),
 - place an “x” in the Pending Analysis column (E),
 - select the priority in eight column (H),
 - and optionally enter any pertinent comments in the ninth column (I).
- The 10th Column (J) has controls to make entering the sample data easier. Double click on the cell to perform the operation in that cell. For an ARF with many samples the **COPY ROW** control followed by the excel fill down operation can be used in increase efficiency.
- Place each sample in the appropriate storage location next to the computer station. If the samples are high activity samples, ask the FAL manager for further assistance. As samples are picked up from the storage location, change the status of the sample in the spreadsheet to “Pending Analysis” by placing an “x” in the Column E for that sample.

- 9.
10. Upon completion of the analysis and review of the results, change the status of the sample to “Reported” in by placing an “x” in the Column F for that sample. Place completed samples in the “Return to FRMAC” location. When the courier arrives to pick up samples, transfer the chain of custody of the samples back to FRMAC by signing the appropriate chain of custody line on the ARF. Be sure to have the courier sign as accepting possession of the sample(s). If possible, make a copy of the ARF, retain the copy, and provide the original ARF to the courier.
- 10.

4.3.2 Samples for Non-routine Analysis

There is potential in the FAL to receive samples for shipping screening or from another participating agency. Samples without an accompanying ARF fall within the scope of this section. As such they will not have the typical chain of custody on the ARF nor the guarantee of contamination and hazard screening.

1. Ensure that before receiving samples there has been a hazards screen for excess activity on the sample and removable contamination. The results of the screen shall be commutated to the FAL personnel in writing with the signature of the certified Radiological Control Technician who performed the screening.
- 11.
2. Confirm that all the samples have a chain-of-custody (COC) and they are all listed on the form.
- 12.
3. Have the courier of the samples sign the line the COC form indicating that the samples are now leaving their possession.
- 13.
4. Sign the line the COC form (FRMAC Fly Away Laboratory) are now in custody of the samples.
- 14.
5. Place the samples in the designated drop-off point.
6. Log the sample into the FAL login excel sheet created for the current event, as in Figure 4.2.
7. Enter the sample information by filling out the form:
 - A unique identifying number either provided by the customer or if the sample is for shipping screening number prepended with PRCL then a number in the first column (A),
 - A unique number grouping the samples or “Shipping” if the sample is for shipping screening in the second column (B),
 - requested Analysis in the third column (C),
 - sample matrix in the fourth column (D),
 - place an “x” in the Pending Analysis column (E),
 - select the priority in eight column (H),
 - and optionally enter any pertinent comments in the ninth column (I).

8. The 10th Column (J) has controls to make entering the sample data easier. Double click on the cell to perform the operation in that cell. For an ARF with many samples the **COPY ROW** control followed by the excel fill down operation can be used in increase efficiency.
- 15.
9. Place each sample in the appropriate storage location next to the computer station. If the samples are high activity samples, ask the FAL manager for further assistance. As samples are picked up from the storage location, change the status of the sample in the spreadsheet to “Pending Analysis” by placing an “x” in the Column E for that sample.
- 16.
10. Upon completion of the analysis and review of the results, change the status of the sample to “Reported” in by placing an “x” in the Column F for that sample. Place completed samples in the “Return to FRMAC” location. When the courier arrives to pick up samples, transfer the chain of custody of the samples back to the customer by signing the appropriate line on the COC. Be sure to have the courier sign as accepting possession of the sample(s). If possible, make a copy of the COC, retain the copy, and provide the original COC to the courier.

Section 5: Logistics

Table of Contents

5.1	Fly Away Laboratory Overview	2
5.2	Equipment Load-Out.....	2
5.3	On-Site Equipment Needs.....	2
5.4	Safety Hazards and Required Facility.....	3
5.5	Communication Requirements	3

Figures

Figure 5.1:	Fly Away Laboratory Floor Diagram.....	4
-------------	--	---

5.1 Fly Away Laboratory Overview

The DOE FAL is an asset capable of transporting its equipment via commercial, contract, military, or charter aircraft. The laboratory equipment is located at the Remote Sensing Laboratory (RSL) in Nevada and deployed as part of CMRT I. FAL personnel shall be responsible for developing instrument capabilities, ensuring personnel are trained on the calibration and use of the instrumentation, and ensuring that all equipment is available for immediate deployment when called upon.

Deployed equipment is capable of analyzing samples for alpha-, beta-, and gamma-emitting radionuclides.. They can process all types of samples including, but not limited to: ground deposition, air filters, swipes, and liquid samples. However, no sample preparation capability is available in the FAL and samples must be analyzed in the containers in which they are collected except for air filters and smears which can be carefully removed from their container and placed in the counting instrument.

The equipment is “exercised” regularly to ensure that the equipment is ready to be used on short notice, and that personnel maintain training on the equipment.

Figure 5.1 provides an example layout of the Fly Away Laboratory processes. Due to the proximity of the counting equipment, some analyses may be impacted by the samples submitted to the FAL for analysis. For example, if a high activity sample is received for iSOLO analysis, the background counts of the gamma spectroscopy units may be impacted. It is important to be aware of this and make use of shielding and recounting of backgrounds to account for it.

5.2 Equipment Load-Out

If possible, a minimum of two of each of the following instruments will be maintained at the RSL:

- Gamma Detector, Associated Computers, Software, Printers, and Standard Sources
- Radon Compensating Alpha/Beta Counter (iSOLO™), Associated Computer, Software, Printers, and Standard Sources

NOTE: It is acceptable to have a single network printer for the entire Fly Away Laboratory.

5.3 On-Site Equipment Needs

The following are the on-site equipment needs:

- Six 6-ft tables
- Two 4-ft tables
- Six chairs
- Sample Storage containers
- Refrigeration capabilities (if required)

5.4 Safety Hazards and Required Facility

- Handling of radioactive sources and samples will be necessary. One should keep radiation exposure as low as reasonably achievable (ALARA) by minimizing the handling of sources and sample material. Care shall be exercised in handling samples according to their associated hazards, whether they are a biological, chemical, and/or radiological.
- When the potential for external contamination exists on the sample container(s), protective gloves shall always be worn while handling the samples.
- The operation of a germanium detector requires a high voltage of 3 to 5 KV at a few mA. Caution must be exercised to avoid touching any high voltage connections. Much of the FAL equipment operates on Li-ion batteries. Inspect all batteries prior to use for cracks, swelling, and signs of leakage. Dispose of damaged batteries appropriately and replace with equivalent equipment.
-
- Work in the Fly Away Laboratory may require working outdoors in possibly extreme conditions. Watch for snakes, rodents, insects, and other potentially hazardous flora or fauna. Be aware of changing weather conditions and immediately follow all orders regarding the protection of your health and safety. Care should be taken when lifting heavy weights to avoid personal injuries.
- The following are facility requirements:
 - Climate controlled 150 ft² lockable building/tent
 - When not performing 24hr operations, a locked facility or security force is required to protect the equipment when not in use.
 - Sample storage area/tent (size dependent on the size of the incident)
 - 110V power with a minimum of 12 outlets
 - Generator fueled for 24 hour operations in the event of an extended power outage
 - Located near Sample Control Tent (desirable)

5.5 Communication Requirements

The following are the communication requirements:

- Email access to forward electronic results
- Internet access
- Wireless hotspot
- Telephone and fax line




Figure 5.1: Fly Away Laboratory Floor Diagram

Section 6: Gamma Spectroscopy Procedures

Table of Contents

6.1	Purpose	3
6.2	Scope.....	3
6.3	Summary of Method.....	3
6.4	Apparatus and Materials	3
6.5	Routine Operations.....	4
6.5.1	On-site Setup of the FALCON™	4
6.5.2	Initializing the High Voltage	7
6.5.3	Quality Control (QC) Check	8
6.5.4	Performing a Background	9
6.5.5	Gamma Library Creation	10
6.5.6	Sample Analysis.....	11
6.5.7	Performing a Background Check (Blank).....	14
6.5.3	ISOCS Check	15
6.6	Non-Routine Operations.....	16
6.6.1	Calibration.....	16
6.6.2	Initial Setup from Factory (New FALCON™ Unit)	22
6.6.3	Acceptance Testing	38

Figures

Figure 6.1:	FALCON 5000™ Power Setup	5
Figure 6.2:	FALCON 5000™ Control/Display Panel.....	5
Figure 6.3:	FALCON 5000™ Battery ports and connectors.....	6
Figure 6.4:	FALCON 5000™ Control/Display Panel.....	6
Figure 6.6:	Energy Calibration Curves Window Showing Peaks.....	18
Figure 6.7:	Energy Calibration Curves Window Showing the Shape Curve	18
Figure 6.8:	Placement of Foam Spacers to Avoid Damage to Connector	24
Figure 6.9:	Access to the RS232 Port underneath the Display/Control Panel	25
Figure 6.10:	Example of the HyperTerminal	26
Figure 6.11:	Example of the detector.txt File	37
Figure 6.12:	Example of Data To Be Copied to detector.txt on the Machine	38

Tables

Table 6.1: Calibration Descriptions	12
Table 6.2: Routine Analysis Required Sample Information.....	13
Table 6.3: Suggested Calibration Values	17
Table 6.4: FALCON 5000™ MCA Input Definition (MID) Settings Part 1	30
Table 6.5: FALCON 5000™ MCA Input Definition (MID) Settings Part 2	31
Table 6.6: QC QAF File Settings CNTRD and FWHM.....	32
Table 6.7: QC QAF File Settings for DCA.....	33
Table 6.8: BKG QAF File Settings	33
Table 6.9: ISX/LCS QAF File Settings.....	33
Table 6.10: Required Executable Files	35
Table 6.11: Required CAM files	35
Table 6.12: Required Template (.tpl) Files	35
Table 6.13: Required Calibration Files	36
Table 6.14: Example iSOCS™ Characterization Files	37

6.1 Purpose

The purpose of this procedure is to describe the proper use of the FALCON™ portable gamma spectroscopy system. The following activities are documented in this procedure:

- On-Site Setup of the FALCON™
- Quality Control
- Sample Preparation
- Sample Analysis
- Calibration of the FALCON™
- Maintenance and Acceptance Testing

6.2 Scope

The FALCON™ 5000 is an electronically-cooled high purity germanium detector. This highly mobile portable gamma spectrometer can rapidly provide nuclide identification and quantification for gamma emitting isotopes in calibrated geometries. iSOCS™ calibration files can be quickly and easily generated in the field for many geometries, freeing the user from the requirement of having calibrated geometries prior to analysis. This capability allows for timely and accurate analysis for almost any sample that may be collected in the field. The FALCON™ is an instrument that can provide accurate and timely information under demanding circumstances.

6.3 Summary of Method

The FALCON™ 5000 can identify and quantify gamma emitting radionuclides of interest using the established geometries and libraries. iSOCS™ can be used to accomplish similar tasks, but it allows for more flexibility in the geometry. However, in analyses involving samples with a high atomic mass, high density, and/or heavy materials, one must be aware of the attenuation effects in the methodology and make appropriate considerations in the modeling.

6.4 Apparatus and Materials

- FALCON™ 5000 High Purity Germanium Gamma Spectroscopy System
- Laptop computer with Windows
- HyperTerminal program
- RS232 (serial) cable
- Radioactive mixed gamma sources
- External DC power supply
- Lithium-ion batteries
- Collimator
- Genie™ 2000 software
- FAL γ -RATS script and accompanying files
- Latex gloves or equivalent (i.e., Nitrile Gloves)
- In-Situ Object Calibration Software (iSOCS™)

6.5 Routine Operations

6.5.1 On-site Setup of the FALCON™

Specific Required Equipment (Refer to FALCON™ Inventory List in ARMS):

- FALCON™ 5000
- Power Supply
- Power Cable (Power Supply to FALCON™)
- Computer
- Computer Power Supply
- LAN Cable
- FALCON™ Batteries (more than one may be required for this procedure).

Optional Equipment:

- Extension Cord
- Keyboard
- Mouse
- Printer
- USB Printer Cable
- Network Switch.

6.5.1.2 Setup of FALCON™ with Access to Electricity

1. Unpack the detector, accompanying power supply, batteries (2 per unit), and associated cable.
 - a. Inspect the FALCON™ unit for any defects or missing parts.
 - b. Inspect the power supply for any damaged or frayed cords.
 - c. Inspect the batteries for damage, leakage, or corrosion.
1. Place the FALCON™ detector on a hard, flat surface or wooden base where you intend to count samples. Situate the FALCON™ so that it is unlikely to get wet or have excessive contact with dirt or other substances that may hinder effectiveness.
2. Place the power supply close to the FALCON™ in a location where it is unlikely to get wet or excessively dirty or be in the line of sight between the detector crystal and the sample. Attempt to keep the power supply a few feet away from any surge protectors, transformers, or generators to avoid electronic interference with the detector.
3. Ensure the power supply is set to the off position.
4. Attach the power supply to the FALCON™ with the gray power cable. This is the only cable that fits in the appropriate holes. See Figure 6.1 below.



Figure 6.1: FALCON 5000™ Power Setup

5. Attach the LAN cable from the FALCON™ to the computer.
6. If desired, attach mouse, keyboard, and printer to computer.
7. Plug both the FALCON™ power supply and computer power supply into a power outlet.
8. Turn the FALCON™ power supply on.
9. Turn on the FALCON™ by pressing and holding the black button on the back panel of the FALCON™ near the base.
10. The FALCON™ begins to cool itself electronically while in standby mode. This process may take up to 4 hours.
11. There is a digital display on the top of the FALCON™ on the detector side. See Figure 6.2 below.




Figure 6.2: FALCON 5000™ Control/Display Panel

12. When the FALCON™ is not ready for use, a red light appears under the Temp High label. When this light is on, the high voltage is locked out and the FALCON™ is unable to operate. When the temperature has fallen to an acceptable range, the red light goes out and a green light under the label Temp Normal lights up.
13. On the same panel as in the previous step, there is a large blue button **STANDBY/OPERATE**. When turning the FALCON™ on, a yellow light is on next to the label **STANDBY**. When the green temperature light is lit, hold the blue **STANDBY/OPERATE** button for about 3 seconds, until the green light next to **OPERATE** turns on.
14. The Green light under **COMM LAN** should be on; if not, check the cable on both ends and make sure the tablet computer is on.
15. Continue to [Section 6.5.2, Initializing the High Voltage](#).

6.5.1.3 Setup of FALCON™ with Batteries

1. Place the FALCON™ detector on a hard, flat surface or wooden base where you intend to count samples. Situate the FALCON™ so that it is unlikely to get wet or have excessive contact with dirt or other substances that may hinder effectiveness.
2. Remove the battery panel, which is on the back of the FALCON™ near the top; it is a black panel with four thumb screws. The FALCON™ should look as shown in Figure 6.3.




Figure 6.3: FALCON 5000™ Battery ports and connectors

3. Inspect the two batteries for any bulging, cracking, or leaking. Dispose and replace damaged batteries appropriately.
4. Install the two batteries, one in each slot by sliding the battery into its slot and plugging in the white clips. Replace the foam behind the batteries so that they do not slide around.
5. Replace the cover and hand tighten the screws (**do not use a screw driver**).
6. Attach the LAN cable from the FALCON™ to the computer.
7. If desired, attach a mouse, keyboard, and printer to the computer.
8. Turn on the FALCON™ by pressing the black button on the back panel of the FALCON™, near the base.
9. The FALCON™ takes about 4 hours to cool depending on the ambient temperature. The batteries last less than 3 hours. A “hot swap” is required to complete the cool down.
10. On the top of the detector near the front is a white panel. See Figure 6.4 below:




Figure 6.4: FALCON 5000™ Control/Display Panel

11. Watch the battery power level indicator. If the yellow light goes out and the red light comes on, this indicates that the power level in the batteries is less than 25%. Remove the battery cover.

12. To perform a hot swap of the batteries, change out the batteries one at a time. If you remove both batteries, the detector quickly heats back up, and you will have to reinitiate the cooling process.
13. Replace the battery panel and hand tighten the screws.
14. When the FALCON™ is not ready for use, a red light appears under the Temp High label. When this light is on, the high voltage is locked out and the FALCON™ is unable to operate. When the temperature has fallen to an acceptable range, the red light goes out and a green light under the label Temp Normal lights up.
15. On the same panel as in the previous step, there is a large blue button **STANDBY/OPERATE**. When turning the FALCON™ on, a yellow light is on next to the label **STANDBY**. When the green temperature light is lit, hold the blue **STANDBY/OPERATE** button for about 3 seconds, until the green light next to **OPERATE** turns on.
16. The green light under **COMM LAN** should be on; if not, check the cable on both ends and make sure the tablet computer is on.

6.5.2 Initializing the High Voltage

1. At this point, the FALCON™ should be setup and cooled down to the operating temperature. The green light next to the “Operate” label should be lit. If not, repeat the above steps.
2. Open the folder “Genie 2000” on the Windows desktop.
3. Inside the Genie 2000 folder, double click on the “Gamma Acquisition and Analysis” file.
4. Open the detector by going to **FILE**, and then select **OPEN DATA SOURCE**. This opens a new window.
5. Near the center of the window are two radio buttons: file and detector. Click the detector radio button. This will populate a list of detectors that have been installed on this computer.
6. Select the appropriate detector (i.e., FAL03 or FAL05) and then click **OPEN**. If you receive an error indicating that the required hardware is unavailable, a system reboot of the computer and/or the detector may be necessary. Completely cycling the power to the FALCON (pressing the button on the back of the unit, waiting 3-5 seconds and pressing it on again) usually resolves this issue. If the problem persists, consult the troubleshooting guide.
7. Near the top left of the screen, select **MCA** and then click **ADJUST**. This will open a new window near the bottom of the screen.
8. Near the top of the new screen are several radio buttons. Select the HVPS (High Voltage Power Supply) tab.
9. In the middle left of the window are two buttons under **STATUS**. Select the **ON** radio button. In the top left of this window, a sign that says “Wait” appears. If the detector is not defined on the system refer to the manufacturer’s detector sheet for the appropriate voltage to apply.
10. Wait until this sign goes away; it will take between 10 and 30 seconds.
11. Place the QC source on the detector; refer to [Section 6.5.3, Quality Control \(QC\) Check](#), for instructions on how to place the source.

12. To the left of the black screen in the Genie 2000 window are several buttons: **START**, **STOP**, **EXPAND** and **CLEAR**. Press the **START** button.
13. The FALCON™ begins to acquire and display the spectrum on the screen. If desired, click the **EXPAND** button, which opens a new screen above the main screen that displays a zoomed-in portion of the spectrum. You can adjust the expanded view by moving the white box that has appeared in the primary screen to move the zoomed section left and right, and you can zoom in and out with the up and down arrow keys.
14. Ensure that the following is true:
 - 1274.53 keV peak is approximately in channel 3480.
 - 86.54 keV peak is approximately in channel 237.
15. If the peaks need adjusting, press **STOP** and then press **CLEAR** and wait about a minute and try again by pressing **START**. If after 3 attempts the peaks do not appear where they should, a gain adjustment may be needed. To adjust the gain navigate to **MCA** and then click **ADJUST**. Click the **GAIN** radio button and adjust the gain until the peaks fall in the correct channels. Seek guidance from the FAL Manager of assistance.
16. If the peaks are in their anticipated locations, close this window by clicking the **X** in the top right of the screen. When a pop-up appears asking if you want to save your changes, select **NO**.
17. Continue to [Section 6.5.3, Quality Control \(QC\) Check](#).

6.5.3 Quality Control (QC) Check

A quality control check must be run at the beginning of a shift and at the end of a batch of samples. If the case occurs that a batch spans a shift, the QC check must be run at the beginning of the shift. A batch of samples comprises of up to 20 samples, including the quality control check and background check.

1. Place the quality control source in the correct position, typically centered on the face of the collimator or cover.
2. Launch the γ -RATS script if it is not already running.
3. Select the detector in the **INPUT** combo box if it is not already selected.
4. Select the **DAILY QUALITY** radio button in the **COUNT TYPE** section. The library, geometry, background, count time, quantity, sample date and sample time should load with the appropriate information. Do not change these parameters unless instructed to do so by the FAL manager.
5. Enter your analyst initials in the **ANALYST** text box.
6. In the **SAMPLE NUMBER** text box enter Q[YY][MM][DD][N], where the bracketed values are replaced with:
 1. [YY] – 2-digit year
 2. [MM] – 2-digit month
 3. [DD] – 2-digit day
 4. [N] – 1-digit indicating the number QC checks run that day
7. Press the **COUNT** button.
8. Next, the script procedure automatically clears the MCA, acquires a spectrum, and analyzes and performs a peak centroid, efficiency, and FWHM check. The QA values automatically update the specified Quality Assurance File (QAF). The quality

assurance report is then sent to the Genie2K report review screen below the spectrum view in a newly opened data source with the name that matches the sample number:

- a. Review the spectrum to ensure that the expected peaks are present.
- b. If no parameters are flagged on the report, the system is ready for use.
- c. If any of the parameters of the quality assurance report fall outside the control limits, another quality assurance measurement should be performed.
- d. If the second count returns any parameter that falls outside the control limit, tag the detector as out of service and investigate the problem. Record the instrument as out of service in the instrument logbook. Consult the FAL manager to determine the next appropriate action.

NOTE: If the error message “Detector not available” appears at this point, check to make sure that the detector is not open in another application window. Also, make sure that the detector is in the “operate” mode and the green LED light is on. If this still does not fix the problem, perform the following steps:

- a. Close the QC program.
- b. Place the detector in standby mode.
- c. Reset the VDM (Virtual Data Manager).
- d. Place the detector in the “Operate” mode.
- e. Restart the HVPS.
- f. Restart the QC program.

Finally, if these steps do not work, power cycle the instrument by pressing the power button on the back panel, waiting 3-5 seconds, and then pressing it again to power the instrument back on.

NOTE: Should the error “Too few points to perform test” appears, simply click OK and rerun the QC measurement until there are enough points.

6.5.4 Performing a Background

During a response, radiological conditions (i.e., background) could change drastically from time to time. It is very important to have a spectrum that characterizes the environmental background when performing gamma spectroscopy. The Background measured in this section is used for subtracting the ambient radiation and is verified by periodic blank measurements, See [6.5.7 Performing a Background Check \(Blank\)](#). This requires measuring the background and entering the results into a Quality Assurance File that the blank measurements can check against.

NOTE: This section shall be performed as part of the deployment setup of the Falcon.

NOTE: If the blank falls outside the prescribed limits, it is very important to take a new background measurement. This includes geometries that require the collimator to be removed. In such cases if the sample provides shielding count a blank sample matrix in the same geometry. Perform this section for all geometries that deviate enough that the blank falls outside the prescribed limits.

1. Launch the γ -RATS script if it is not already running.
2. Select the detector in the **INPUT** combo box if it is not already selected.

3. Select the **BACKGROUND** radio button in the **COUNT TYPE** section. The library, geometry, background, count time, quantity, sample date and sample time should load with the appropriate information.
4. Enter your analyst initials in the **ANALYST** text box.
5. In the **SAMPLE NUMBER** text box enter B[YY][MM][DD][N], where the bracketed values are replaced with:
 - a. [YY] – 2-digit year
 - b. [MM] – 2-digit month
 - c. [DD] – 2-digit day
 - d. [N] – 1-digit indicating the number QC checks run that day
6. Press the **COUNT** button.
7. Make a note of the filename, sample number, and count conditions present during the background so the spectrum can be reused if necessary.
8. Wait for the count to finish.
9. When the analysis is complete, the file is saved with name in the format [NN]_FAL_[YY][MM][DD] where the bracketed values are replaced with:
 - a. [YY] – 2-digit year
 - b. [MM] – 2-digit month
 - c. [DD] – 2-digit day
 - d. [NN] – 2-digit number of the Falcon.During a routine analysis, you can choose this background to be subtracted from a sample spectrum or select **LATEST** to use the latest. A report will print displaying the total counts in three regions.
10. Open the Bkg.QAF file for the background in the Quality Assurance Editor (C:\Genie2k\EXEFILES\qa.exe).
11. Select Edit-defs → Parameter Definitions... and press **MORE...**
12. Under the User Driven Tests (cps) enter the results from the background count found on the report for the corresponding parameter in the **MEAN** text box.
13. Enter 10% of the Mean in the Std Dev text box.
14. Move to the next parameter by clicking in **NEXT** button.
15. Repeat steps 12-14 for all the parameters.
16. When finished, click **OK** to close the Full Parameter Edit window, and **OK** to Close the Parameter Definition Edit window.
17. Select File → Save, then close the Quality Assurance Editor.
18. Record the background in the instrument logbook and take note of any non-routine or special reasons why the background was collected.

6.5.5 Gamma Library Creation

The automatic electronic data deliverable (EDD) generator for the FALCON™ will force a Region of Interest (ROI) and calculate an activity for every nuclide in the library independent of whether the nuclide was detected or not. To avoid reporting undetected nuclides, a gamma library should be created upon arrival that contains only the nuclides of interest for that event and any others that happen to be detected on the sample.

1. Determine the nuclides of interest by finding the requested nuclides on the Analysis Request Form. It may be necessary to add nuclides as they appear in the spectra of specific samples.
2. If necessary, open the “Genie 2000” program group by double clicking the icon.
3. Double click on the icon titled **NUCLIDE LIBRARY EDITOR**.
4. In the top section of the Nuclide Library Editor, enter the information into the fields for the Nuclide Name (e.g. Co-60), Half-Life, and Uncertainty. Be sure the appropriate radio button is selected for half-life units. Press the **Add Nuclide** button at the bottom of the window and the information entered will appear in the lower section.
5. In the center section, enter the information into the Energy, Abundance, and Uncertainty (left field is for energy uncertainty and the right field is for abundance uncertainty) fields. Uncertainty is entered at 1-sigma. If the energy line is the most abundant and does not interfere with any other nuclide lines, select the Key Line check box. Press the **Add Line** button and the line will appear below the nuclide specified in the top section.
6. If the nuclide has more gamma lines, overwrite the information in the center section and press the **Add Line** button.

NOTE: Only one nuclide line can be the key line for a nuclide; this will appear as an asterisk in front of the energy. The software will honor the last line added with the Key Line check box checked.

NOTE: It may be easier to pare down an existing library than to create a new one. To do so, open a large existing library and save as a new name. Begin removing nuclides by selecting them in the lower section and pressing the **Delete** button. Save the file and close the Nuclide Library Editor.

7. Check all the entries against a reputable source for accuracy and correctness. Due to the tedious nature of library creation and the need for high accuracy, have another FAL member check the entries.
8. Select **SAVE AS** command from the Nuclide Library Editor. In the **FILE NAME** field, enter a meaningful name (e.g. the event name) for the library with the extension NLB. In the **DESCRIPTION** field enter a meaningful description.
9. Click on the OK button to save the Library file. The Library file is saved in the directory C:\genie2K\camfiles with the name given in Step 8 and the extension NLB. It will now be available for use in Gamma RATS in the library drop-down menu.

6.5.6 Sample Analysis

1. Place the sample in the appropriate geometry that matches the calibrations or iSOCS model on the machine.
2. Launch the γ -RATS script if it is not already running.
3. Select the detector in the **INPUT** combo box if it is not already selected.
4. Select the **SAMPLE** radio button in the **COUNT TYPE** section.

NOTE: The **CUSTOM ASF** can also be selected for an analysis that differs from the standard analysis. Enter the sample type (CAM Parameter: STYPE) in the box and browse for the Analysis Sequence File (ASF) to be used.

5. Select Library (e.g., FRMAC.nlb).
6. Select a geometry (e.g., AF0AT3F). If no calibrated geometry is available, refer to [Appendix A](#) of this manual to create an efficiency calibration using iSOCS™. Note that a sample can be counted with a “dummy” calibration file and reanalyzed with the proper mathematical efficiency model later. Table 6.1 describes commonly encountered calibrations that are performed on the FALCON™.
7. Select the geometry accuracy radio button underneath the Geometries.
 - a. Select **Regular** if the sample exactly matches the calibrated geometry in matrix, location, and size.
 - b. Select **Similar** if the sample is like the calibrated geometry in matrix, location, or size. Note that this selection will apply a caveat to the analytical report stating that the counting geometry was imprecise and could lead to biases in the results. This option is to only be used when the deviation from the calibrated geometry is minor. For example, if the calibrated geometry is one gallon of water in a Cubitaner counted against the collimator face, but the sample is 0.95 gallons of water in the same container and counted in the same location, the **Similar** option should be used.
 - c. Select **Irregular** if the sample was not counted in a configuration that was calibrated for or if the sample was not close to the calibration standard. This will lead to a caveat on the report that states that the results are to be used as identification only. Quantification is impossible when the sample was counted in a configuration that was not calibrated for or modeled.

17.

Table 6.1 shows the common calibrations performed on the FALCON™ system.

Table 6.1: Calibration Descriptions

Calibration Name	Description
#AF2.CAL	2-inch glass fiber air filter on contact with collimator cover
#CUB.CAL	1-Liter Cubitaner filled with water counted on the collimator cover
#SGLD.CAL	Gladware container with approximately 500 grams of soil counted on contact with the collimator cover with the larger surface facing the detector. Typically used for ground deposition samples.
#AFCC.CAL	2-inch face loaded charcoal cartridge counted with the inlet side on contact with the collimator cover.
Suffix	Description
AT1FT	Sample was counted exactly 1 foot and on axis with the detector collimator face. Typically used for samples that cause dead time to exceed 10% when on contact.
AT3FT	Sample was counted exactly 3 feet and on axis with the detector collimator face. Typically used for samples that cause dead time to exceed 10% when at 1 ft.

NOTE: # denotes the detector number that the calibration applies to.

8. Background Subtraction:
 - a. Uncheck the box if a background has not yet been run. If one has not been run yet, the background can be subtracted later in a reanalysis of the spectrum.
 - b. If a background has been run and analyzed, place a check in the **SUBTRACT BKG** box.
 - c. Choose the background count that most closely characterizes the environmental radiation levels at the time of sample acquisition. "Latest" will find the last run background. Check the instrument logbook for information regarding the backgrounds. If there is any doubt as to what background to use, or if a new background should be run, consult the FAL manager.

NOTE: In most portable count situations, the acquisition time for the background should be set to the same acquisition time or longer as the sample for which the background analyses will be applied. However, the software will make time corrections if the count times differ.

NOTE: In practice, the environmental background is taken prior to sample analysis. While this is possible in most situations, samples may need to be counted prior to the determination of background. This is acceptable if it can be shown that the environmental levels of radiation had not changed between the sample measurement and the background measurement. The sample spectrum must be reanalyzed with the most applicable background. If the detector is moved, a new background must be taken. Record any detector movements or changes in the radiological environment in the instrument logbook.

9. Enter count time for the analysis in seconds. The minimum count time is determined by the FAL manager. This is done using the required critical level which is indicated on the ARF. Or the required count time indicated on the ARF.
10. Enter your analyst initials in the **ANALYST** text box.
11. In the **SAMPLE NUMBER** text box enter the SCF identification number (e.g., SCF-0001).
12. Enter the sample quantity and select the appropriate units. Ensure that the selected unit matches the units from the requested critical level.
13. Enter or select the Sample Date (i.e., the date to which the nuclides will be decay corrected) and the sample time in a 24-hour format (hh:mm).
14. Once data acquisition is complete, the spectrum is analyzed, and a detailed report is generated along with an electronic comma separated variable (csv) file.
15. Carefully review the analysis report for mistakes or problems with the data. Sign and date the "Analyzed by" line on the report.
16. Have the report reviewed a second time by another FAL staff that is trained in gamma spectroscopy.
17. Import the .csv file into excel and enter the remaining information. The information is outlined in Table 6.2

Table 6.2: Routine Analysis Required Sample Information
FALCON™ Sample Input Parameters

Analysis Request #	This must match the tracking number on the analysis request form (e.g. ARF-00002)
QC Batch ID	ARF numbering appended with a letter (e.g. ARF-0005-A)
Sample Matrix	Pull Down (Air Filter, Feed, Food, Instrument, Milk, Moving Air Filter, Moving Instrument, Other, Soil Swipe, Vegetation, Water) – match what is written on the ARF
Moisture Property	*only applies to soils. If the soil was dried in a laboratory and the mass entered was the dry mass, select dry . If the sample was not dried and the wet mass was used as the aliquot, select wet . For matrices other than soil, or if no soil mass was used as the aliquot, select N/A .

18.

Samples that are analyzed by the FAL gamma spectrometer can be reanalyzed with different efficiency files, libraries, backgrounds, etc. at any time.

18. Launch the γ -RATS script if it is not already running.
19. Select “file” in the **INPUT** combo box if it is not already selected.
20. Browse for the file by pressing the ... button next to Sample number. This will load the information into the form.
21. Make the desired changes and Press **RE-ANALYZE**.

NOTE: Checking the “Use Stored ASF” box will use the Analysis Sequence File (ASF) stored in the CAM File and not the ASF associated with the sample type.

6.5.7 Performing a Background Check (Blank)

Background check ensures the environmental background still represents the ambient background and can be used for background subtraction. A background check must be measured to confirm the background *once per quality control batch*.

1. Remove all sources of radiation away from the detector.
2. Launch the γ -RATS script if it is not already running.
3. Select the detector in the **INPUT** combo box if it is not already selected.
4. Select the **BLANK** radio button in the **COUNT TYPE** section. The library, geometry, background, count time, quantity, sample date and sample time should load with the appropriate information.
5. Enter your analyst initials in the **ANALYST** text box.
6. In the **SAMPLE NUMBER** text box enter C[YY][MM][DD][N], where the bracketed values are replaced with:
 - [YY] – 2-digit year
 - [MM] – 2-digit month
 - [DD] – 2-digit day
 - [N] – 1-digit indicating the number QC checks run that day
7. Press the **COUNT** button.
9. Next, the script procedure automatically clears the MCA, acquires a spectrum, and analyzes and performs a peak centroid, efficiency, and FWHM check. The blank values automatically update the specified Quality Assurance File (QAF). The quality assurance report is then sent to the Genie2K report review screen below the spectrum view in a new data source matching the configured file name for blanks:

- g. Review the spectrum to ensure that there no unexpected peaks present.
- h. If no parameters are flagged on the report, the system is ready for use.
- i. If any of the parameters of the quality assurance report outside the control limits, another blank measurement should be performed.
- j. If the second count returns any parameter outside the investigation limit, a new environmental background must be run. Consult [6.5.4 Performing a Background](#).

6.5.3 ISOCS Check

An ISOCS control check must be run quarterly. Place the ISOCS check source control source in the correct position, typically in the jig with the collimator removed.

1. Launch the γ -RATS script if it is not already running.
2. Select the detector in the **INPUT** combo box if it is not already selected.
3. Select the **ISOCS CHECK** radio button in the **COUNT TYPE** section. The library, geometry, background, count time, quantity, sample date and sample time should load with the appropriate information. Do not change these parameters unless instructed to do so by the FAL manager.
4. Enter your analyst initials in the **ANALYST** text box.
5. In the **SAMPLE NUMBER** text box enter I[YY][MM][DD][N], where the bracketed values are replaced with:
 1. [YY] – 2-digit year
 2. [MM] – 2-digit month
 3. [DD] – 2-digit day
 4. [N] – 1-digit indicating the number QC checks run that day
6. Press the **COUNT** button.
7. Next, the script procedure automatically clears the MCA, acquires a spectrum, and analyzes and performs a peak centroid, efficiency, and FWHM check. The QA values automatically update the specified Quality Assurance File (QAF). The quality assurance report is then sent to the Genie2K report review screen below the spectrum view in a newly opened data source with the name that matches the sample number:
 - e. Review the spectrum to ensure that the expected peaks are present.
 - f. If no parameters are flagged on the report, the system is ready for use.
 - g. If any of the parameters of the quality assurance report fall outside the control limits, another quality assurance measurement should be performed.
 - h. If the second count returns any parameter that falls outside the control limit, tag the detector as out of service and investigate the problem. Record the instrument as out of service in the instrument logbook. Consult the FAL manager to determine the next appropriate action.

NOTE: If the error message “Detector not available” appears at this point, check to make sure that the detector is not open in another application window. Also, make sure that the detector is in the “operate” mode and the green LED light is on. If this still does not fix the problem, perform the following steps:

- k. Close the QC program.
 1. Place the detector in standby mode.

- m. Reset the VDM (Virtual Data Manager).
- n. Place the detector in the “Operate” mode.
- o. Restart the HVPS.
- p. Restart the QC program.

Finally, if these steps do not work, power cycle the instrument by pressing the power button on the back panel, waiting 3-5 seconds, and then pressing it again to power the instrument back on.

NOTE: Should the error “Too few points to perform test” appears, simply click OK and rerun the QC measurement until there are enough points.

6.6 Non-Routine Operations

6.6.1 Calibration

6.6.1.1 Certificate Creation

Certificate creation can be performed by several methods in Genie™. The following presents the recommended method. It is acceptable for an experienced user of Genie™ to use short-cuts. Genie™ references a user selected certificate as a reference point to determine the energy dependent efficiencies.

1. With the assistance of the FAL Manager, select an appropriate NIST Traceable source for a calibration. Each source comes with a certificate declaring the radionuclides in the source, their activity, and reference date.
2. If necessary, open the “Genie 2000” program group by double clicking the icon.
3. Double click on the icon titled **CERTIFICATE FILE EDITOR**.
4. At the top third of the Certificate File Editor screen are entry fields for Title, Quantity, and Assay Date. Edit the Title information to include source manufacturer, source geometry, and manufacturer’s source number. Enter “1” in the sample Quantity field. Edit the Assay Date to reflect the date and time of source fabrication.

NOTE: The Assay Date is used for decay correction during efficiency calibrations. Enter the Assay Date in the format mm-dd-yy hh:mm:ss AM or PM. (**Example:** 03-01-99 12:00:00 PM.)

5. In the center of the screen are the fields Nuclide, Half-Life, Energy, Half-Life Uncertainty, Emission Rate and Emission Rate Uncertainty. Be sure the appropriate radio button is selected for the Half-Life units. Uncertainty is entered at 1-sigma, some conversion from the certificate value may be necessary.

NOTE: You are allowed only one line per nuclide. If more than one line is being used for the calibration, you need to enter the nuclide twice, such as 1173 KeV and 1332 KeV for Co-60.

6. Check all entries against the original source certificate for accuracy and correctness. Due to the tedious nature of certificate creation and the need for high accuracy, also have another FAL member check the entries.

7. Select the **SAVE AS** command from the Certificate File Editor File menu. In the **FILE NAME** field, enter the manufacturer source number with the extension CTF. In the **DESCRIPTION** field, enter the source geometry.
8. Click on the **OK** button to save the certificate file. The certificate file is saved in directory C:\genie2k\camfiles with the manufacturer source number for file name and with the extension “CTF.”

6.6.1.2 Initial Energy Calibration

An initial energy calibration is recommended **ONLY** when setting up a new instrument or after receiving an instrument from the manufacturer following any repairs. The point of the initial energy calibration is to align the peaks to their correct channel based on 3000keV at channel 8192.

1. The following points are suggested values to use for a standard 30 – 3000 keV range:

Table 6.3: Suggested Calibration Values

Nuclide	Energy(keV)	Channel
Am241	59.9	163
Cs137	661.2	1809
Co60	1173.2	3203
Co60	1332.5	3638

2. To determine the correct channel for the source being used or desired energies, a simple ratio can be applied by dividing the 8192 ch/3000 keV.
3. Take each energy peak in keV and multiply by the ratio. Round to the nearest whole number to obtain the channel. Note these channels and energies for later use.
4. Open the gamma acquisition and analysis window.
5. From the File menu select **OPEN DATASOURCE...**
6. Select the Falcon unit.
7. If any spectrum counts are present, clear the spectrum.
8. Begin a count ensuing that as close to 10,000 counts are collected in several peaks across the energy spectrum.
9. From the Calibrate menu, select **ENERGY ONLY CALIBRATION...**
10. Enter the energy and channel, and then click **ACCEPT** for each peak.
11. Delete the peaks if necessary by selecting the peak and click **DELETE**.
12. After entering all peaks, click the **SHOW...** button.




Figure 6.6: Energy Calibration Curves Window Showing Peaks

13. The peaks are represented as green squares. They should all line up on the blue line.
14. Select **SHAPE** to view the shape curve. This curve should be hyperbolic (square root ($y=\sqrt{x}$) shape).
- 19.




Figure 6.7: Energy Calibration Curves Window Showing the Shape Curve

15. Each square should line on the curve or close to it.
16. After verifying the points, click **OK** to exit out of the curves.
17. When complete, click **OK** to complete the energy calibration.
18. Place a source on the detector face. The following steps assume that an Am-241, Cs-137, and Co-60 source is being used. Make the necessary adjustments for different sources.
19. Adjust the present time to at least 1000 seconds. If the deadtime of the detector is >50% you will need to move the source further away from the detector.
20. Click on MCA menu.
21. Select **ACQUIRE SETUP**.
22. Ensure that seconds is selected.

23. Enter 1000.
24. Select **OK** to exit.
25. Click **START** under Acquire to begin counting.
26. Adjust the ADC zero, amplifier gain, and fine gain until the 59.5 keV line from Am-241 and 1332.5 keV line from Co-60 are approximately at the desired channels (**Example:** Channel 162 and Channel 3639, respectively, for a 3000 keV/8192 channel relationship).

NOTE: Use the Clear button to erase spectral data after adjustment of the amplifier gain and fine gain.

27. Adjust the ADC Lower Level Discriminator (LLD) setting so that the channels representing the first 35 keV are clear.
28. When adjustments have been made, stop the count by clicking **STOP**.
29. Exit out the gamma acquisition and analysis window. When prompted by the software, select that you wish to save the changes.
30. Record this calibration in the instrument logbook and proceed to [Section 6.6.1.3, Energy and Shape \(FWHM\) Calibration](#).

6.6.1.3 *Energy and Shape (FWHM) Calibration*

The following steps should use National Institute of Standards in Technology (NIST) radioactive sources that are not available in the FAL load out. This procedure can be performed in the field with any source of known energies if necessary. When performing the calibration, the deadtime of the detector should be kept below 50%. To decrease the deadtime you will need to move the source further away from the detector.

1. Open the detector in Genie2K.
- 20.

NOTE: If this is the first energy calibration after the initial calibration a prompt may appear that mentions a questionable calibration. Select “yes” and continue the procedure.

2. Place the source on the collimator face.
3. Clear the existing spectrum (if any) by pressing the **CLEAR** button. Set the preset by navigating to MCA → Acquire Setup... and enter a preset time that ensures that most of the source peaks have an area of at least 10,000 counts.
4. Click **START** under Acquire to begin counting.
3. Once the spectrum has been acquired perform a Peak Locate and Peak Area analysis by navigating to Analysis → 1 Execute Sequence → FAL Peaks. This should generate a peak search report and send it to the printer as well as generate region of interests (ROIs) around the prominent peaks.
4. Navigate to Calibrate → Energy Full → By Certificate File... and select the desired certificate (e.g. ENERGY.CTF). This file should contain all the relevant peaks for radionuclides present in the source that was used.
5. Move the ROI index to the peak that corresponds to the highlighted energy from the certificate using the + and – Buttons. Once the ROI index aligns with the highlighted line press the **CURSOR** button. The Channel, FWHM and Low Tail should calculate.

NOTE: If the Low tail remains at zero low tail is not activated. To activate the low tail: navigate to Calibrate → Setup... and check the Low radio button under the Tail Curves section.

6. Repeat Step 5 until all peaks have values for Channel, FWHM and Low Tail.
7. View the Calibration curve by pressing **SHOW...**
8. It is recommended to not remove outliers that are at the lowest and highest end of the energy spectrum. These are needed to bound the calibration. If they appear to be undesirable, consult with the FAL Manager. Once outliers are moved they cannot be retrieved. To remove outliers:
 - a. Count the green data points from the left to the right.
 - b. Enter the number of the peak you wish to drop in the small dialog box labeled “Peak:”
 - c. Click **DROP PK** to drop the peak from the calibration.
 - d. Repeat this process for all outliers.
9. When complete and if a printer is available, click on the **PRINT** button to obtain a hard copy of the energy and shape calibration curves. Click on the available radio button to toggle between energy and shape curves.
10. Click on the **OK** button to terminate the “Energy Calibration Curve” screen.
11. Navigate to Calibrate → Store...
12. Save the spectrum as C:\genie2k\calfiles\E#YYMMDD.cal, where # is the detector number and YYMMDD is the year, month, and day the calibration is performed.
13. Print the energy calibration reports by navigating to Analyze → L Reporting → 1 Standard...
 - a. Select the CALIB.tpl for the template name
 - b. Select ECAL for the section
 - c. Change error Multiplier to 2.0
 - d. Check **PRINTER** in the Output to Section
 - e. Press **EXECUTE**.
14. Click the save icon to save the information to the MCA buffer. Close the data source, Click “no” when prompted to save changes. The file has already been saved.
15. Obtain a copy of the Portable Gamma Spectroscopy Calibration checklist and approval form from in [Appendix B](#).
16. Fill out the form and attach the supporting documents on the checklist. Retain this paperwork for filing with the efficiency calibration packages.
17. Record this calibration in the instrument logbook.

6.6.1.4 Efficiency Calibration

1. Run the daily quality control check prior to performing the efficiency calibration to ensure that the detector is functioning properly.

NOTE: If this is the first calibration for the detector or a calibration after major repairs the Quality Control Check can be bypassed.

2. Make sure a background has been taken in the same orientation that the detector is in to ensure that there will be no interfering lines with the calibration.

3. Obtain a mixed-nuclide standard in the geometry of interest. Do not use the source used for quality control checks. If necessary, create a certificate file as described in the [Section 6.6.1.1, Certificate Creation](#).
4. Open the detector in Genie2K.
5. Place the source in the correct geometry.
6. Clear the existing spectrum if any by press the **CLEAR** button. Set the preset by navigating to MCA → Acquire Setup... and enter a preset that ensure that most of the source peaks have an area of at least 10,000 counts.

NOTE: the following steps are for calibrating with cascade summing corrections on, if cascade summing is not to be used in analysis Navigate to Analysis → 1 Execute Sequence → FAL Peaks and skip to step 9 then skip step 11. It is recommended that cascade summing corrections are always used.

7. Click **START** under Acquire to being counting.
8. Once the spectrum has been acquired, perform a Peak Locate and Peak Area analysis by navigating to Analysis → 1 Execute Sequence → FAL Calibration Peaks. Select any calibration file (it does not matter which as it will be overwritten) and press **LOAD**.
9. Select the corresponding ISOCS geometry and press **SELECT**. This will process the spectrum and generate a report.
10. Navigate to Calibrate → Efficiency → By Certificate File... and select the desired certificate (e.g. Cubitaner.CTF).
11. Press the **AUTO** button to fill out the Efficiency and Error for each peak.
12. Check Perform Cascade Correction.
 - a. The Geometry Composer File should auto fill. If it does not, press Select and browse to the corresponding ISOCS geometry file. The geometry file must be on the instrument computer in the following folder:
C:\GENIE2K\isocs\data\GEOMETRY and have been actually run on the computer (not just transferred from another computer) to work correctly.
 - b. Check Use ISOCS/LabSOCS Total Efficiencies and Detector Characterized for LabSOCS.
 - c. Press **AUTO** and note the peaks that are corrected for cascade summing are marked with an asterisk.
13. If using a dual calibration fit model, select the peak just below 100 keV and press **CROSS-OVER**. An “X” will appear next to the error of the peak selected. It is best to select the peak nearest the crest (maximum) of the calibration curve as the cross-over peak.
14. Press Show... to review the calibration curve. Select the model that best fits the points and adjust the order for the best fit. Make a note of the model chosen. If the dual model is selected make sure the curves match well (i.e. first derivatives are roughly equal). A good fit is characterized by one inflection point, smooth between the points, and passes through or close to the points.
15. Close the Efficiency Calibration Curves window by pressing **OK**, then close the Efficiency Calibration window by Pressing **OK**.
16. Navigate to calibrate → Store
 - a. Name the calibration file name as [detector number][geometry name][YYMMDD] where values in the brackets are replaced by the detector

- number, the geometry name and the date in the format 2 digit year, 2 digit month and 2 digit day, respectively.
- b. It is helpful to fill out the **EFF. GEOM ID** with the geometry name.
 - c. Press **STORE** to finish.
17. Close the Geine2k window. Do not save by pressing **NO**.
 18. Launch the γ -RATS script if it is not already running.
 19. Expand the **NON-ROUTINE** section.
 20. Select the model noted above, enter the geometry name and browse for the stored calibration file.
 21. Press **SET CALIBRATION** and the new geometry will appear in the geometry box.
 22. Open the file just created (C:\GENIE2K\CALFILES*.cal where * is the file name configured in the gamma.ini file) in Genie2K and generate the calibration report.
 - a. Analyze → L Reporting → 1 Standard...
 - b. CALIB.TPL for the template, EffCal for the **SECTION NAME**, 2.0 for the **ERROR MULTIPLIER** and output to **PRINTER** checked.
 - c. Press **EXECUTE**.
 23. Print the Calibration graphs by navigating to Calibrate → Efficiency Show... and pressing **PRINT**. Print both in Linear and Log scale, use the radio button in Scale section to toggle between the two.
 24. Count an identical source (preferably a different source than the one used for calibration if possible) using the [6.5.6 Sample Analysis using the FALCON™](#). Verify (at a minimum) that a low (<70 keV), mid (500-800 keV), and high (>1200 keV) values match the certified values to within +/- 20%. Retain the analysis report and the bias calculations for the calibration package.
 25. Obtain a copy of Gamma Spectroscopy Efficiency Calibration checklist and approval form from [Appendix B](#).
 26. Fill out the form and attach the supporting documents according to the checklist. Next, sign the “Reviewed By” line and have the FAL Manager or designee approve the form.
 27. File the efficiency calibration package in accordance with FRMAC processes.
 28. Record each calibration in the instrument logbook.

6.6.2 Initial Setup from Factory (New FALCON™ Unit)

This section describes how to connect and set up the FALCON™ 5000 portable gamma spectrometers. **The section should only be used if it is the initial setup of the detector or the detector was sent back to the factory and everything needs to be reinstalled.**

6.6.2.1 Required Equipment

- FALCON™ 5000 portable High Purity Germanium Detector with integrated MCA
- Laptop computer with Windows
- HyperTerminal program
- RS232(serial) cable
- Virtual RS232 port via USB if applicable
- Radioactive Source (mixed gamma) and holding jig issued by Canberra
- External DC Power Package

- Lithium-ion batteries
- Tungsten Collimator
- Genie™ 2000 Software

6.6.2.2 PPE Requirement

None

6.6.2.3 Setup Procedure

1. Unpack the detector, the accompanying power supply, batteries (2 per unit), and associated cables.
2. Inspect the FALCON™ unit for any defects, missing parts, and the protective detector cap.
3. Inspect the power supply for any damage or frayed cords.
4. Inspect the batteries for damage, leakage, or corrosion.
5. If anything is damaged or out of place, contact the manufacturer's service representative to report any damage.
6. Assign a name to the detector (FAL##, where ## is a number).
7. Place a label with the assigned name on the detector.
8. Remove the battery compartment screws on the back of the FALCON™.
9. Install the batteries such that each battery slides easily into each battery compartment. If there is any resistance in sliding the battery, remove the battery and re-adjust the orientation of the batteries. The electrical connection of the battery should extend toward the back of the FALCON™.
10. Connect the battery's electrical connection to the left side of the unit located inside the battery compartment. The release clip on the connector should point toward the front of the unit.
11. The batteries are shipped with two rectangular pieces of foam, one per battery. Install the foam on the right side of the electrical connection. As seen in Figure 6.8, the battery wire should not contact the right side of the battery compartment.
- 21.


***INCORRECT******CORRECT***

Figure 6.8: Placement of Foam Spacers to Avoid Damage to Connector

12. Place the battery compartment cover back into place. Hand-tighten all four bolts. **Do not use a screwdriver.**
13. Connect external power supply to the FALCON™ unit.
14. Remove protective end cap and screw on collimator.
15. Switch the power switch to the on position on the power supply.
16. Press and hold the power button on the FALCON™, until the power LED on top of the unit is on.
17. Each unit requires up to **4 hours** to reach normal operating temperature depending on the initial conditions in the room.
18. When the cryostat reaches the desired temperature, the temperature light indicates **NORMAL**. If after 6 hours the temperature light does not indicate normal, this may be a failure of the cryostat mechanism. Report this to the FAL manager.

6.6.2.4 Establishing the Local Area Network (LAN)

Every FALCON™ (from the manufacturer) is set up with the wireless LAN enabled. If the unit is purchased with a tablet computer, the computer also has the “WIFI” enabled. In both instances, the “WIFI” needs to be disabled. While disabling the WIFI, the wired LAN has to be enabled to allow communication with the computer.

NOTE: Performing the following steps to disable the WIFI requires a computer with a serial port or a computer with a serial port adapter and a COM port communication software (HyperTerminal is use described but others PowerShell, putty, etc. are acceptable).

1. If a USB to Serial adaptor is being used the computer port must be setup prior to connection. If a normal serial cable is being used, skip to step 8.
2. Connect the serial adapter to a USB port on the computer.
3. Right click on My Computer and select Manage.
4. Click on Device Manager.
5. Scroll down to Ports, right click, and select Scan for Hardware.
6. Insert the USB to Serial adapter driver CD and follow the prompt to install the driver.
7. Take note of the port name that the computer assigns the new hardware (i.e. COM4), this will be the port that you must assign the HyperTerminal connection to.
8. If applicable, shutdown the FALCON™ unit by pressing and holding the off button on the FALCON™ unit.
9. The top of the FALCON™ unit has a LED display that shows the status of the unit. Remove the four hex socket heads that hold down the LED display.

CAUTION: Do not perform these steps while the unit is powered up. This may lead to an electric shock or damage to the unit.

NOTE: Do not pull hard on the LED display cover as it is attached by wires.

10. Slightly lift the display cover. Inside is a ribbon cable with the RS232 female connection. Pull out the cable, being careful not to pull the RS232 from the unit, but enough to allow access to the port (Figure 6.9).




Figure 6.9: Access to the RS232 Port underneath the Display/Control Panel

11. Attach the RS232 cable to the FALCON™, and then attach it to the computer's serial cable.
12. Open the HyperTerminal program located in the Windows startup menu (**All Programs > Accessories > Communications**).
13. The HyperTerminal program prompts for the new connection name. Enter "FALCON."
14. Select the communications port (it will mostly likely be COM1, but it may also be whatever the program selects as the default COM port). Enter the following communication properties:

- Baud rate: 57600 bits per second
 - Data bits: 8 data bits
 - No Parity
 - 2 stop bits
 - No flow control.
15. Now that the HyperTerminal is setup, hold down the **W** key and at the same time power up the FALCON™ via the push button. Hold both the **W** key and the power button until all the lights are lit on the LED display cover. Release the power button and then the **W** key.
 16. Once the connection is established, not only with all the LEDs be lit, but the HyperTerminal displays the following (Figure 6.10):

```
Change Setup:
0 Server
1 Channel 1
2 Channel 2
3 E-mail
4 WLAN
5 Expert

6 Security
7 Defaults
8 Exit without save
9 Save and exit          Your choice ? 0

Network mode: 0=Wired Only, 1=Wireless Only, 2=Bridging(One Host) (1) ? 0

IP Address : (192) .(000) .(000) .(100)
Set Gateway IP Address (N) ?
Netmask: Number of Bits for Host Part (0=default) (0)
Change telnet config password (N) ?
```

Figure 6.10: Example of the HyperTerminal

17. Press **0 SERVER**.
18. Press **0** again to shift to “Wired only.”
19. If not already set, set the IP address of 192.0.0.###, where ### is the three-digit detector ID number (e.g., FAL03 would have an IP address of 192.0.0.003).
20. Set the net mask as 255.255.255.0, and the default ‘No’ to change telnet config password.
21. Press **9** to save and exit.
22. Power off the FALCON™ unit, and remove the serial cable from the computer and the FALCON™ unit.
23. Tuck the FALCON™’s serial cable back into its case and screw down each hex head bolt.
24. HyperTerminal may be closed out. Connect the LAN cable to the units LAN connection, as well as to the computer. If the computer is already connected to a network, a network switch or router needs to be obtained. If connecting to a switch or router the I.P. address in the FALCON™ may need to be changed to conform to the network gateway.

NOTE: Contact the computer's system administrator to setup the network connections if the computer is having trouble communicating with the FALCON™.

6.6.2.5 Software Installation

1. Consult the FAL Manager or designee before installation to verify the correct versions of all installation software (i.e., Genie™ 2000).

NOTE: There may be computers where CD-ROM installation is not available; it is acceptable to install from a remote drive instead; consult the FAL Manager.

2. Insert the Genie™ 2000 Basic Spectroscopy CD in the CD-ROM in the computer.
3. Click on the Windows Start menu.
4. Select **RUN**.
5. Type in the drive letter followed by the colon symbol (e.g., d:).
6. Click on **SETUP.EXE**. This loads the Genie™ 2000 menu.

Sentinel Driver Installation

NOTE: The Sentinel Drivers come with Genie™ 2000 starting with version 3.2.

1. Select Install/Update Sentinel Driver.
2. Follow the setup and accept the defaults.
3. For setup type, select **COMPLETE**.

Genie 2000 Basic Spectroscopy Installation

1. Select **INSTALL GENIE™ 2000**.
2. Select the default language.
3. Select **INSTALL GENIE™ 2000 S504 INSPECTOR BASIC SPECTROSCOPY** for the install type.
4. Accept the terms of the license.
5. Installation prompts to verify installation to destination folder of c:\genie2k. Click **NEXT**.
6. Install the Genie™ 2000 documentation and click **NEXT**.
7. Verify correct setup and click **NEXT**.
8. Select **STANDARD** install and click **NEXT**.

SNAP Driver Installation

1. Do not exit out of the CD-ROM. Open the following directory:
d:\Bin\G2KVx.x.x\XP_Vista, where x.x.x is the version number. Verify that the aimsnap5.inf file is present.
2. The CD-ROM may be closed out.
3. Click on the Start Menu.
4. Go to My Network Places. If it is not located in the Start Menu, it is in the control panel.
5. On the left side of the My Network Places screen, click on **VIEW NETWORK CONNECTIONS**.
6. Right click on **LOCAL AREA CONNECTION**. Select any connection to edit.
7. Select **PROPERTIES**.

8. Select **INTERNET PROTOCOL (TCP/IP)**.
9. Click **INSTALL**.
10. Select **PROTOCOL** and then **ADD**.
11. Click on **HAVE DISK**.
12. Select **BROWSE**.
13. On the Locate File dialog box under Look in, find the CD-ROM drive.
14. Locate the aimsnap5.inf located on the CD-ROM under the directory above.
15. Select the aimsnap5.inf and then **OPEN**.
16. On the Install from disk dialog, click **OK**.
17. Click **OK** for the Canberra NDIS 5.0 SNAP Protocol Driver Vx.x, where x.x is the version number of the SNAP driver.
18. Close out all the windows and restart the computer.

Gamma Analysis Software Installation

1. Remove the Basic Spectroscopy CD and insert the Gamma Analysis Software
2. Click on the Windows Start menu.
3. Select **RUN**.
4. Type in “d:” without the quotation marks if d: is the drive letter for the CD-ROM drive.
5. Click on **SETUP.EXE**.
6. Select **ENGLISH** and then accept the licensing agreement.
7. The program loads a series of applications in the directory “c:\Documents and Settings\All Users\Start Menu\Programs\Genie-2000.”
8. Press the **DIRECTORY** button (it looks like a folder with an arrow coming out of it).
9. Right click the Genie 2000 folder and copy.
10. Close out all windows.
11. On the desktop, right click and select paste. This action pastes a copy of the Genie 2000 folder.
12. Open the folder and verify that the icons for applications are in the Genie 2000 folder.

Interactive Peak Fit Software Installation

NOTE: Interactive Peak Fit Version 1.3.1 is the first version of software contained on a CD. All previous versions are contained on a 3.5” floppy disk. If the version of Interactive Peak fit is on a floppy disk, open the setup.exe from the a: drive.

1. Remove the Gamma Analysis Software CD and insert the Interactive Peak Fit CD.
2. Open the CD by the same method as the other two CDs.
3. Start the setup.exe file.
4. Select **ENGLISH** and accept the licensing agreement.
5. The Interactive Peak fit will install and then close out of all windows.

Quality Assurance Installation

NOTE: Insert the USB thumb drive to a port on the computer.

1. Open the disk in the same manner as the CDs except instead of a “d:” drive substitute with the name of the USB drive. (i.e., “e:/”).
2. Click on the setup.exe file and select the defaults.

3. The directory “c:\Documents and Settings\All Users\Start Menu\Programs\Genie-2000” is displayed.
 4. Right click on the Quality Assurance Editor and copy the icon.
 5. Open the Genie2k folder on the desktop and paste the icon in the Genie2k folder.
 6. Select **ENGLISH** and then accept the licensing agreement.
- 22.

Falcon5000 Software Installation

1. Insert the Falcon5000 (S513) Installation disc.
2. Open the disc and run the setup.exe file.
3. Follow the on-screen instructions and agree to all the defaults.

γ -RATS Software Installation

1. Locate the media with the FRMAC FAL files (also on the shire and CMWeb if accessible).
2. Copy the Genie2K folder from the FAL files media the local C:\ drive and replace all the files.
3. Navigate to the GENIE2K folder on the local C:\ drive and copu the γ RATS shortcut to the desktop.

6.6.2.6 *SETUP OF Multi-Channel Analyzer Input Definition (MID) File*

The MID file describes the detector and its parameters.

1. Open the Genie2000 folder on the desktop.
2. Start the MCA Input Definition Editor. If you receive an “ICP node connect” error, uninstall **GENIE™ 2000 S504 INSPECTOR BASIC** and **Gamma Analysis**, then reinstall.
3. On the menu bar, click on **FILE**.
4. Select **NEW**.
5. On the menu bar, click **EDIT**.
6. Select **ADD MCA**.
7. Under the Network MCA’s, select **FALCON™ 5000 USING I2K-F5K**.
8. Click on **ADD**.

9. On the menu bar, click **DEVICES**. For the following parameters under device, select:

Table 6.4: FALCON 5000™ MCA Input Definition (MID) Settings Part 1

MCA	
MCA Full Memory	8k
No of ADCs	1
Acq. Mode	PHA
IP Address	192.0.0.### (where ### is the 3-digit detector number. Ex. FAL03 would have an IP Address of 192.0.0.003)
Stabilizer	
Device Driver	I2K D-Stab
Control	Programmable
Internal	MCA
Power Management	
Device Driver	I2K Power
Control	Programmable
Internal	MCA
DSP Gain	
Device Driver	I2K Gain
Control	Programmable
Internal	MCA
DSP Filter	
Device Driver	I2K Filter
Control	Programmable
Internal	MCA

10. On the menu bar, click **SETTINGS**. For the following parameters under setting, select:

Table 6.5: FALCON 5000™ MCA Input Definition (MID) Settings Part 2

MCA	
None	
Stabilizer (defaults)	
Gain Centroid	7680 ch
Gain window	8 chs
Gain Spacing	64chs
Gain ratio	1.000
Gain rate div	1
Correction rng	Ge
High Voltage	
Range	Above the voltage if positive Below the voltage if negative Must encompass the voltage setting
Voltage Limit	Set slightly beyond the Voltage
Voltage (established at factory)	Voltage setting is located on the falcon and support box. Consult the detector manual to obtain the operating voltage.
Inh signal	Positive
Power Management	
Standby delay	100min
DSP Gain	
Gain Attenuator	Off
FDisc Mode	Auto
LLD Mode	Manual
Fine Gain	1.4001x*
S-fine gain	0.99999%*
Course gain	X40*
FDisc Setting	1.0%
LLD	0.1%*
Inp. Polarity	Negative
Inh. Polarity	Positive
DSP Filter (default settings)	
Rise Time	5.6
BLR mode	Auto
Preamp type	RC
Flat Top	0.8
FDisc shaping	Normal
Input	
Input Name	FALNN (NN is the detector number, ie 03)
DetectorType	Gamma or X Ray – Ge
Input Size (Channels)	8192

* most likely to change during initial setup

11. Save as FALNN, where *NN* is the detector number.
12. Load the database after closing the MID file or the editor.
13. Reopen the MCA Input Definition Editor if necessary.
14. Click on **DATABASE**.
15. Click on **LOAD TO**.
16. Select the newly created MID file and click **LOAD**.
17. Click **DONE**.
18. Close the MCA Input Editor.

6.6.2.7 Setup of the Quality Control QAF Files

The QAF file should only be setup if it is the initial setup of the detector or if the QAF file needs to be recreated. The QAF stores quality data about each QC/BKG/ISX/LCS performed and the QC parameters. A source should be chosen such that the dead time of the detector is less than 3%, and there are at least three gamma emissions in the low (<100 keV), Mid (100-1100 keV), and High (>1100 keV). The library for the QAF will have to be changed to account for the energy lines described below (Tables 6.6, 6.7, and 6.8). The recommended settings of the control limits (**UPPER** and **LOWER** in the Parameter Editor) are:

- FWHM: $\pm 15\%$ of the baseline,
- DCA: $\pm 15\%$ of the baseline,
- CNTRD: $\pm \frac{1}{2}$ of the FWHM at the energy,
- Background: $\pm 10\%$ of environmental background measurement,
- ISX/LCS: Between $\pm 25\%$ of the certified value

where the baselines are determined by at least 5 QC Runs.

1. Open the Quality Assurance Editor.
- 23.
24. **NOTE:** If an error appears that reads “Add-Defs menu creation error: “2”, you must reinstall the quality assurance editor.
25.
 2. Select **FILE** on the menu bar select “new”.
 3. For the peak centroid, navigate to **ADD-DEFS** → **PEAK SEARCH** → **PEAK CENTROID**.

Table 6.6: QC QAF File Settings CNTRD and FWHM

Description	Low CNTRD/FWHM	Mid CNTRD/FWHM	High CNTRD/FWHM
Name (analysis type)	PSCENTRD	PSCENTRD	PSCENTRD
Energy Line	low	mid	high
Conv. Factor	1.00	1.00	1.00
Units:	keV	keV	keV
Boundary Driven Test	Checked	Checked	Checked

4. Select **OK** to close out parameter window.
5. Repeat for all three centroid parameters
6. For the full width at half maximum parameters, navigate to **ADD-DEFS** → **PEAK SEARCH** → **PEAK FWHM**.
7. Select **OK** to close out parameter window.
8. Repeat for all three FWHM parameters.

9. For the decay corrected activity parameters, navigate to **ADD-DEFS** → **ENERGY LINE** → **DECAY CORRECTED ACTIVITY**.

Table 6.7: QC QAF File Settings for DCA

Description	Low DCA	Mid DCA	High DCA
Name (analysis type)	NLACTVTY	NLACTVTY	NLACTVTY
Store Error	Low Nuclide	Mid Nuclide	High Nuclide
Energy Line	Low	Mid	High
Conv. Factor	1	1	1
Units:	DCA	DCA	DCA
Boundary Driven Test	Checked	Checked	Checked

10. Select **OK** to close out parameter window.
11. Repeat for all three DCA parameters
12. Save the file as DQC.qaf.
13. Open a new file **FILE** → **NEW**.
14. Navigate to **ADD-DEFS** → **BACKGROUND** → **BACKGROUND COUNT RATE...**

Table 6.8: BKG QAF File Settings

Description	Background Low	Background Mid	Background High
Name (analysis type)	NLACTVTY	NLACTVTY	NLACTVTY
Nuclide	Low Nuclide	Mid Nuclide	High Nuclide
Start Chan	100	1093	2185
End Chan	1092	2184	8192
Conv. Factor	1	1	1
Units:	cps	cps	cps
Boundary Driven Test	Checked	Checked	Checked

15. Select **OK** to close out parameter window.
16. Repeat for all three background parameters.
17. Save the file as BKG.QAF.
18. Open a new file **FILE** → **NEW**.
19. Navigate to **ADD-DEFS** → **NUCLIDE** → **WTD MEAN ACTIVITY...**

Table 6.9: ISX/LCS QAF File Settings

Description	Low	Mid	High
Name (analysis type)	NCLWTMEAN	NCLWTMEAN	NCLWTMEAN
Nuclide	Low Nuclide	Mid Nuclide	High Nuclide
Conv. Factor	1	1	1
Units:	Bq/unit	Bq/unit	Bq/unit
Boundary Driven Test	Checked	Checked	Checked

20. Select **OK** to close out parameter window.
21. Repeat for all three ISX/LCS parameters
22. Save the File as ISX.QAF or LCS.QAF.

6.6.2.8 Source Certificate Setup

Source certificates are used for efficiency and energy calibrations. It is the electronic version of the paper certificate that comes from the source's manufacturer in a format that the Canberra software can read. Certificate files can be imported from other machines. All certificate files go in C:/Genie2k/camfiles/. Also, obtain a copy of the manufacturer's source certificate to keep with the instrument files.

1. Open the Genie 2000 folder on the desktop.
2. Start the Certificate File Editor.
3. Certificate files are created in the same manner as the library files.
4. In the title text box, enter "Certificate for {source ID}," where sourced *ID* is the source name or source serial number.
5. Enter 1 for quantity.
6. Enter the assay date for the source. This is typically called the reference time.
7. On the menu bar, select **OPTIONS**.
8. Select **LIBRARY EXTRACT**.
9. To enter a new nuclide, for example Am-241, select the A_D.nlb file.
10. Scroll down to find Am-241.
11. If the activity on the paper source certificate is in Becquerel or Curies, enter the value and uncertainty, and click Change and then **OK**. The conversion to gammas per sec and its uncertainty are calculated in the main screen. Uncertainty is entered at 1 sigma, a conversion from the certificate value may be necessary.
12. If the activity units are not in Becquerel or Curies, either convert the activity to either Becquerel or Curies, or enter that conversion factor into the box, and click **CHANGE** and then **OK**.
13. If the activity on the source certificate is in gamma per second, enter "1" for both the activity and the uncertainty, and click **CHANGE** and **OK**.
14. In the Emission Rate box, enter the correct gamma per second value from the paper certificate and its uncertainty, and click **CHANGE**.
15. If this energy line is to be used as part of a calibration, click on the **USE FOR CALIB/INIT**.
16. Enter the emission rate uncertainty at 1-sigma.

NOTE: Certificates vary in what coverage factor ($k=1,2$ or 3) that is printed on the certificate. Be aware of this and make sure the value entered in the electronic file is the 1-sigma combined standard uncertainty of the emission rate.

17. If there are multiple energy lines for one nuclide, ensure each line has the correct emission rate and uncertainty entered.
18. Perform these steps for each additional nuclide.
19. Select **FILE** then **REPORT** to obtain a copy of the electronic report

NOTE: The report displays the uncertainty at the 2-sigma level (which assumes the value was entered as the 1-sigma combined standard uncertainty).

20. When complete, have another FAL member review your work for consistency. The creator and reviewer should date and initial the paperwork and file with the instrument records.

26.

6.6.2.9 Setting the Defaults

The γ -RATS script allows defaults (libraries, geometries, count times, etc.) to be set for different count types.

1. Launch the γ -RATS script if it is not already running.
2. Select the detector in the **INPUT** combo box if it is not already selected.
3. Select the desired count type radio button in the **COUNT TYPE** section.
4. Select the desired Library, geometry, geometry accuracy, background, count time, quantity, quantity unit, sample date, sample time.
5. Expand the **NON-ROUTINE** section.
6. If QA parameters are necessary for reporting, press the **SELECT QAF...** button and browse to the desired QAF.
7. Review the inputs and press the **SET DEFAULT** button.
8. Press **OK** to confirm.

6.6.2.10 Necessary Files

Many of the support files listed below have already been created. To take advantage of existing support files, copy each of the files listed below from their storage locations to the local computer (Tables 6.9 - 6.14). These files are deployed in the correct directory structure can simply be merged with the existing Genie2K directory.

Copy the following files to the C:\GENIE2K\ directory on the local computer:

Table 6.10: Required Executable Files

γ RATS.ps1
gamma.ini
γ RATS.ico
γ RATS shortcut

Copy the following files to the C:\GENIE2K\CAMFILE directory on the local computer:

Table 6.11: Required CAM files

ENERGY.CTF	DQC.NLB
FAL.NLB	BKG.ROI
DQC.NLB	MIXED_GAMMA.NLB

Copy the following files to the c:\genie2k\ctlfiles directory on the local computer:

Table 6.12: Required Template (.tpl) Files

CALIB.TPL	QARPT.TPL*
FAL.TPL	CERTLIS.TPL*
EDD.TPL	FALPEAKS.ASF
BLK.ASF	BKG.ASF
CALPEAKS.ASF	LSC.ASF
DQC.ASF	ISX.ASF
ROUTINE.ASF	

*override these files in the ctlfiles directory.

Copy the following files to the C:\GENIE2K\CALFILES directory on the local computer:

Table 6.13: Required Calibration Files

DEFAULT.CAL	EMPTYSHLD.CAL
QC.CAL	

Next, the script shortcut should be established on the computer's desktop. This will allow users to easily run the script.

1. Navigate to C:\GENIE2K\.
2. Copy the γ RATS shortcut.
3. Paste on the desktop.

6.6.2.11 iSOCS™ Installation and Detector Characterization File Setup

1. Close the VDM (virtual data manager) and all other Windows programs that may be open. To do this, right click on the icon in the bottom right corner of the screen and select "Close"....
2. Insert the iSOCS™ disc.
3. Click on the Windows Start menu.
4. Select **RUN**.
5. Type in "d:" without the quotation marks, where d: is the drive letter for the CD-ROM drive.
6. Click on **SETUP.EXE**.
7. Click **INSTALL ISOCS**.
8. Be sure to use the default directory structures suggested by the setup program.

NOTE: To use iSOCS™ correctly, the detector must have been characterized by Canberra, and you must have the characterization files on-hand. Two files of interest include the *.par file, which contains the characterization data, and the detector.txt file, which includes instructions that iSOCS™ uses to find the *.par file. The following steps detail how and where to place these files in the default directory structure so that iSOCS™ can run correctly.

9. Insert the iSOCS™ characterization disc for the detector that is to be used. The disc will be marked with the Canberra issued serial number for the detector.
10. Using Windows Explorer, open the disc to view the files. An example of the files that are included in the disc are shown in Table 6.15 below.

27.

Table 6.14: Example iSOCS™ Characterization Files

Filename	Description
33P20828.par	This file contains all of the detector characterization data for detector #33p20828
ACK_718384_SN_33P20828_CHAR.pdf	This file is the validation package of the characterization process for detector #33p20828
detector.txt	This file contains instructions that allow iSOCS™ to find the *.par files for all the detectors on the machine
DETutil.exe	This is an executable that installs the .par files automatically (This will not be used, the placement of the .par file will be done manually)
Readme.txt	This lists instructions for the install of the characterization files

- Open detector.txt with Microsoft Notepad. Figure 6.11 is an example of what the file looks like.

```


# 718384 - Sandia - GC4020 - S/N-33P20828
33P20828,59.22,68.58,0,76.2,133.4,5.2,5.2,26,33P20828.par,4, #
ge,0.41,5.35, #
... #
al,1.6,2.7, #
ge,1.22,5.35, #
al,1.215,2.7, #
al,1.6,2.7, #
ge,0.550,5.35, #
al,3.175,2.7, #
al,5.0,2.7

# 'Example' DETECTOR
=====
Example,71.0,61.0,0,88.9,150,5,5,26,Example.par,4, # continued row symbol
ge,0.77,5.35, #
... #
AL,1.6,2.7, #
Ge,1.0,5.35, #
AL,1.03,2.7, #
AL,1.6,2.7, #
Ge,1.0937,5.35, #
AL,3.15,2.7, #
AL, 5, 2.7

```

Figure 6.11: Example of the detector.txt File

- In line two of the file, edit the first parameter (in this example “33p20828”) so that it reads as the name of the detector that is to be used (ex. FAL04). This is the name of the detector that will be shown in the list of characterized detectors.
- Save the file.
- Copy the group of data for the detector that is to be used. In this example, the data that is to be copied is as follows (Figure 6.12):



```

# 718384 - Sandia - GC4020 - S/N-33P20828
FAL04,59.22,68.58,0,76.2,133.4,5.2,5.2,26,33P20828.par,4,#
ge,0.41,5.35,#
al,1.6,2.7,#
ge,1.22,5.35,#
al,1.215,2.7,#
al,1.6,2.7,#
ge,0.550,5.35,#
al,3.175,2.7,#
al,5.0,2.7

```

Figure 6.12: Example of Data To Be Copied to *detector.txt* on the Machine

15. Using Windows Explorer, navigate to the following directory:

C:\GENIE2K\isocs\data\PARAMETERS

16. Open the file “detector.txt.”

NOTE: This detector.txt file is different than the one on the characterization disc; it is the file that is used by iSOCS™.

17. Paste in the copied data to the end of the file; be sure to have a blank line between the last group of data and the new group of data.

18. Save the file by clicking **FILE** → **SAVE**.

19. Return to the iSOCS™ characterization disc using Windows Explorer.

20. Copy the file *.par, where * is the detector serial number.

NOTE: Do not change this filename.

21. Go to the directory: C:\GENIE2K\isocs\data\DCG.

22. Paste the *.par file into this directory.

23. Once the above tasks are completed, iSOCS™ can be used to generate efficiency curves for any modeled geometry. See [Appendix A](#) for a tutorial on how to use iSOCS™.

6.6.3 Acceptance Testing

1. Open the GENIE™ folder and start the Gamma Acquisition & Analysis program. Under **FILE**, select **OPEN DATA SOURCE** and select **DETECTOR**. Open the FALNN, where *NN* is the designated detector number.

NOTE: If you experience the “Required Hardware Unavailable” Error, set the FALCON to standby and reset the power. Attempt to open the detector again.

2. Select **MCA** and then **ADJUST** from the menu bar.
3. In the Adjust window, click on the **HVPS** radio button. Click on the **ON** radio button to turn the HV on and wait a few minutes for the system to stabilize.
4. Place the Canberra-provided source (QC source for the detector) on the detector and begin an acquisition.

5. Adjust the Amplifier Gain in the Adjust window. Click on the **GAIN** radio button. Adjust the Course, Fine, or Super Fine to fit the following peaks:
 - 1274.53 keV peak falls in the neighborhood of channel 3480.
 - 86.54 keV peak falls in the neighborhood of channel 237.
28. These channels are a rough fit and are adjusted later in the calibrations to yield an energy calibration curve.
6. If the above step cannot be achieved, contact the Canberra service representative to help adjust the system.
7. Adjust the LLD. On the adjust window click the **GAIN** radio button. Click **NEXT** until the LLD radio button is visible.
8. Click on **MANUAL LLD**.
9. Adjust the LLD percentage. After every adjustment, clear the spectrum and re-start the acquisition. The LLD is the first channel from the left that has counts in it. Adjust the LLD such that the first 30 channels in the spectrum have no counts in them.
10. Record the proper setup and acceptance testing of the detector in the instrument logbook.

This page is intentionally left blank

Section 7: iSOLO™ Procedures

Table of Contents

7.1	Purpose	43
7.2	Scope.....	43
7.3	Summary of Method.....	43
7.4	Interferences and Limitations.....	44
7.5	Equipment.....	44
7.6	Operations Procedure.....	44
7.6.1	Counting Samples	47
7.7	Reporting	49
7.7.1	Printing Reports from iSolo.....	49
7.7.2	Report Generation from iLink interface.....	50
7.7.2	Record Keeping	50
7.7.3	EDD Creation.....	50
7.8	Quality Control.....	51
7.9	References	52
7.10	Document History.....	52
7.11	Calibration.....	52

Figures

Figure 7.1:	Example Main Sample Screen.....	45
Figure 7.2:	QC Screen Shot.....	45
Figure 7.3:	QC Acceptance Screen	45
Figure 7.4:	Alpha QC Standard Screen	46
Figure 7.5:	Alpha QC Acceptance Screen.....	46
Figure 7.6:	Beta QC Standard Screen.....	46
Figure 7.7:	Beta QC Acceptance Screen.....	47
Figure 7.8:	iSOLO™ Data Screen.....	48
Figure 7.10:	Print Menu Screen	49
Figure 7.11:	System Report Screen	50
Figure 7.12:	iSOLO™ Setup Screen	52
Figure 7.13:	Calibration Screen	52

Figure 7.14: Calibration Execution Screen 53

Figure 7.15: Calibration Routine List Screen 53

Figure 7.16: Calibration Type Screen 53

Figure 7.17: Blank Calibration Source Screen 53

Figure 7.18: Blank Calibration Acceptance Screen 54

Figure 7.19: Calibration Type Screen 54

Figure 7.20: Alpha Calibration Source Screen..... 54

Figure 7.21: Alpha Calibration Acceptance Screen 55

Figure 7.22: Calibration Type Screen 55

Figure 7.23: Beta Calibration Source Screen..... 55

Figure 7.24: Beta Calibration Acceptance Screen 55

Figure 7.25: Calibration Completion Screen 56

Tables

Table 7.3: Procedure Selection Table..... 48

Table 7.4: iSOLO™ Report Fields 50

7.1 Purpose

This procedure provides instructions for the calibration and use of the Canberra *iSOLO*™ Radon Compensating Alpha/Beta Counting System (*iSOLO*™) that is used for counting air filters and swipe samples. This detector can provide limited radioisotopic identification (e.g., it can discriminate between radon daughters and plutonium).

7.2 Scope

It is anticipated that the *iSOLO*™ alpha/beta counting equipment will be primarily used to perform field analysis of air filters and smears/swipes in support of the Federal Radiological Measurement and Assessment Center (FRMAC) operations. Air filter results are typically requested by the FRMAC in units of $\mu\text{Ci}/\text{m}^3$. Swipes/smears are typically analyzed to determine if the area smeared meets contamination control criteria, which are generally specified in terms of $\text{dpm}/100\text{ cm}^2$ (or dpm/cm^2).

Data accuracy and reliability require defensible calibrations, quality assurance, and analysis processes and documentation. This section seeks only to establish parameters for the equipment setup relative to these processes.

7.3 Summary of Method

A traditional approach for determining the activity of radionuclides present in the air is based on sampling a measured volume of air through a filter, thus collecting radioactive dust particulates, and measuring the filter later with an alpha/beta counter. The natural presence of Radon and Thoron gas in the atmosphere represents a significant problem when trying to rapidly quantify such an activity (e.g., without waiting for the Radon/Thoron chain to decay). Alpha particles resulting from the decay of Radon/Thoron progeny can down scatter into the lower energy region of the spectrum, where signals indicative of the presence of other radionuclides would normally be detected. It is this interference that must be quantified and corrected for. The Canberra *iSOLO*™ instrument utilizes a series of algorithms to evaluate the Radon and Thoron contribution to the spectrum to dramatically reduce the interference from Radon and Thoron progeny on the long-lived alpha emitting radionuclides.

The *iSOLO*™ provides the system operator with gross alpha/beta results. Pulses from detected charged particles are sorted by energy. These regions of interest allow the user to reasonably determine which nuclide is present in a sample if a highly compensated alpha result is encountered. The following regions may be selected to be reported:

- Total Alpha Region: 3.0 MeV to 9.6 MeV
- Uranium Region: 3.0 MeV to 5.0 MeV
- Uranium, Am and Pu Region: 3.0 MeV to 5.6 MeV
- Curium Region: 3.0 MeV to 6.4 MeV
- Total Beta Region: 125 keV to 2.2 MeV

7.4 Equipment

The iSOLO™ 300G low background Alpha/Beta counters are manufactured by Canberra. These units are portable, firmware based, single sample, manual, gas-less alpha/beta counters designed specifically for the analyses of air filters and smear or swipe samples. The counters weigh less than 19 pounds, use a solid-state silicon PIPS detector, and can be operated for 10 or more hours with internal batteries (nickel metal hydride) after fully charging for about 12 hours.

- iSOLO™
- Sample Holders
 - 25 mm loose filter media (typically used for smears)
 - 47 mm loose filter media (typically used for swipes and air filters)
 - 100 mm loose filter media (typically used for air filters)
 - Standard insert for any non-filter sample type up to 60mm diameter
- Lined Tray to place the iSolo to minimize potential spread of contamination.
- iSOLO™ Log Book with the following information:
 - Air Sample/Swipe Data Sheet
 - Periodic Background and Efficiency QC Sheet
 - Annual Calibration Report
 - Background, Efficiency, QC charts and other iSOLO™ generated reports that support the data entered on the iSOLO™ 1-3 forms listed below.
- NIST Traceable α emitting 25 mm diameter source
- NIST Traceable β emitting 25 mm diameter source

7.5 Operations Procedure

The following instructions cover routine “Background,” “Efficiency QC,” and counting samples on the *iSOLO*™.

1. Turn on the iSOLO™ by turning the switch on the right side of the *iSOLO*™ to the “1” position. The Power LED glows when the instrument is powered. Immediately upon being turned on, the *iSOLO*™ initializes and runs a diagnostic check on the major subsystems.
2. Perform “Background QC” Measurements:
 - a. Verify the instrument is on and ready to count:
 - Verify that the display shows the correct date and time. Adjust system clock to match local time in the settings menu.
 - Verify that the instrument is ready to count indicated by the “Main Sample Screen” below.




Figure 7.1: Example Main Sample Screen

- b. Load blank sample. (use 47 mm sample holder)
3. Activate Daily background check count:
 - a. Press the **BKG** button located in the **DAILY** panel. The **DAILY** panel is located to the left of the main display screen.
 - b. The following screen is displayed:




Figure 7.2: QC Screen Shot

- c. Wait until the count is complete.
- d. Accept the value if it is reasonable (0.0-0.3 cpm for α , and 8.0-25.0 cpm for β).
- e. After the count completes, inspect the values reported for both the α and β counts displayed on main screen below.




Figure 7.3: QC Acceptance Screen

- f. Enter the results into the iSOLO™ Bkg & Eff QC sheet.
- g. Compare results to acceptance ranges and press **ENTER** located in the panel to the right of the screen to accept the count.
- h. If the counts are outside the range, recalibrate by following calibration procedures in [Section 7.11, Calibration](#).
4. Perform “Alpha Efficiency QC” Measurement:
 - a. Unload blank sample and load Am-241 50 mm standard.
 - b. Activate the alpha efficiency count.

- c. Press the **α EFF** button located in the **DAILY** panel. The **DAILY** panel is located to the left of the main screen.
- d. The following screen is displayed:

<p>Daily QC</p> <p>Insert Am-50mm NT567 Src</p> <p>Press Enter</p> <p>to continue</p>

Figure 7.4: Alpha QC Standard Screen

- e. Wait until the count is complete.
- f. Accept the value if reasonable.
- g. After the count completes, inspect the value reported for the α count displayed on the main screen below.

<p>QC PROCEDURE COMPLETE</p> <p>α Efficiency: %</p> <p>Press Enter to Accept</p> <p>Press Cancel to Reject</p>

Figure 7.5: Alpha QC Acceptance Screen

- h. Enter result into iSOLO™ Bkg & Eff QC sheet.
 - i. Compare results to acceptance range on iSOLO™ Bkg & Eff QC sheet and press **ENTER** located in the panel to the right of the screen to accept the count.
 - j. If the count is outside the range, recalibrate by following calibration procedures in [Section 7.11, Calibration](#).
5. Perform “Beta Efficiency QC” Measurements:
 - a. Unload Am-241 α standard and load Sr-90 β 50 mm standard.
 - b. Activate the beta efficiency count.
 - c. Press the **β EFF** button located in the **DAILY** panel. The **DAILY** panel is located to the left of the main display screen.
 - d. The following screen is displayed:

<p>Daily QC</p> <p>Insert Sr-50mm NT566 Src</p> <p>Press Enter</p> <p>to Continue</p>

Figure 7.6: Beta QC Standard Screen

- e. Wait until count is complete.
- f. Accept the value if reasonable.
- g. After the count completes, inspect the value reported for the β count displayed on the main screen below.

QC PROCEDURE COMPLETE	
β efficiency:	%
Press Enter to Accept	
Press Cancel to Reject	

Figure 7.7: Beta QC Acceptance Screen

- h. Enter the result into iSOLO™ Bkg & Eff QC sheet.
- i. Compare result to acceptable range on iSOLO™ Bkg & Eff QC Sheet and press **ENTER** located in the panel to the right of the screen to accept the count.
- j. If the count is outside the range, recalibrate by following calibration procedures in [Section 7.11, Calibration](#).
- k. Unload the β standard.

7.5.1 Counting Samples

1. Load the sample:
 - a. Open sample drawer.
 - b. Select the appropriate sample holder as indicated in Table 7.3.
 - c. Remove the old sample holder by positioning your fingers along the side of the sample slide. From underneath the slide, place your thumbs on the access holes and gently push up on the sample holder. This action releases the sample holder from the sample slide.
 - d. Insert new sample holder by aligning the holes in the sample holder with the post on the slide. Press down firmly.
 - e. Load sample into holder.
 - f. Close the sample drawer.
2. Select Procedure:
 - a. Press **SEL PROCEDURE** to list the procedures available for sample analysis as seen below in Table 7.3, and using the arrow keys, place the cursor ">" beside the procedure of choice for a batch of samples.
 - b. Press **ENTER** to select the procedure.

Table 7.3: Procedure Selection Table

Cursor	Procedure Name	Sample Type	Diameter	Count Time (min)	Sample Holders		
					25 mm	47 mm	100 mm
A	25mm 2 min dpm	Smear	1"	2	X		
B	47mm 2 min dpm	Swipe	1.5" & 2"	2		X	
C	25mm 10 min dpm	Smear	1"	10	X		
D	47mm 10 min dpm	Swipe	1.5" & 2"	10		X	
E	47mm 10 min uCi	Air Filter	2"	10		X	
F	100mm 10 min uCi	Air Filter	4"	10			X
G	47mm 60 min uCi	Extended Air Filter	2"	60		X	
H	100mm 60 min uCi	Extended Air Filter	4"	60			X

- c. Count the first sample or blank.
- d. Press **COUNT** to start the analysis of the first sample.
- e. The green LED **COUNT** key blinks when the sample is finished counting.
- f. Enter the results into the iSOLO™ Hotspot iSOLO™ Data Sheet from screen below.

Date	Time
Procedure	ID
T: min	
α: dpm	
β: dpm	
Radon	
----- Compensated -----	
α: dpm	
β: dpm	

Figure 7.8: iSOLO™ Data Screen

- g. If there are no more samples to be counted using the selected procedure, press **GROUP DONE** to terminate the Group. The following screen is displayed:

Declare Group Done?
1. No
2. Yes

Figure 7.9: Group Done Confirmation Screen

If “Yes,” sample results need to be printed. See [Section 7.7, Reporting](#), for printing instructions.

- h. If counting more than one sample from selected procedure:
 - a. Open sample drawer.
 - b. Place the next sample in the sample holder.
 - c. Close the sample drawer.
 - d. Press **COUNT** again.

- e. Repeat until all samples are counted including the blanks (1 per 20 unknown sample).
- f. When all the samples in a group (e.g., samples counted with the same procedure) have been counted, press **GROUP DONE** to declare this group of samples as complete.
- i. The group done confirmation screen, Figure 7.9 is displayed that asks you to confirm that the group is done.
- j. If another sample needs to be counted as part of this same group, place the cursor ">" by 1 No and press the **ENTER** key. Place another sample in the sample holder and count it as part of this original group.
- k. At the end of each group, print the most recent group results, and file results in iSOLO™ Log Book. Refer to [Section 7.7, Reporting](#), for instructions for printing reports.
- l. Remove sample holder and insert calibration source holder.

7.6 Reporting

At the end of each group, print and file the results.

7.6.1 Printing Reports from iSolo

1. Ensure that the iSOLO™ is connected to the appropriate printer and turned on.

7.6.1.1 Print Most Recent Group:

- a. On the front panel of the iSOLO™ press the **PRINT** key.
- b. Move the cursor to **1, MOST RECENT GRP** from the Print Menu below and press **ENTER**.

PRINT MENU	
Cursor	Description
1	Most Recent Group
2	All Grps
3	Select Grp/Rpt
4	System Reports

Figure 7.10: Print Menu Screen

7.6.1.2 Print System Reports:

- a. On the front panel of the iSOLO™ press the **PRINT** key.
- b. Move the cursor to **4, SYSTEM REPORTS** from the Print Menu above and press **“Enter.”**
- c. Using arrow keys, select system report requested and press **ENTER**.

System Reports	
1	System Params
2	Proc Params
3	QC Report

Figure 7.11: System Report Screen

7.6.2 Report Generation from iLink interface

1. From the desktop, highlight the batch to be reported.
2. In the iLink desktop, enter the sample numbers or QC identifier in the XXX field.
3. Right click the batch number and select Print Report.
4. At the dialog screen, select the reporting template.
5. Select the option to Save As and store a PDF version of the report on the laptop folder located in C:\HotSpot\iSOLO™\Completed\Reports.
6. The PDF can be printed at the user's discretion.

7.6.2 Record Keeping

A report is generated after each Group is completed. The following fields are displayed on the printed report:

Table 7.4: iSOLO™ Report Fields

Sample Date	[Sample date]
Sample Start	[Start time]
Alpha Procedure Activity	[alpha activity (units specified by procedure)]
Beta Procedure Activity	[beta activity (units specified by procedure)]
Alpha (3-6.4 MeV) Procedure Activity	[region alpha activity (units specified by procedure)]
Alpha (3-6.4 MeV) Activity $\pm X$ Sigma	[region alpha total uncertainty]
Alpha (3-6.4MeV) Decision Level	[region alpha decision level (~MDA)]
Beta Comp. Procedure Activity	[Radon comp. beta activity (units specified by procedure)]
Beta Activity $\pm X$ Sigma	[Radon comp. beta uncertainty]
Beta Comp. Decision Level	[Radon comp. beta decision level (~MDA)]

All reports generated by the iSOLO™ must be printed and filed in the Hotspot log book.

NOTE: Sample data is stored in battery-backed memory in the iSOLO™. Data from 300 samples can be stored in this memory at one time. To prevent sample data from being inadvertently overwritten, once 300 sets of sample data are stored, the iSOLO™ halts operation and displays an “Insufficient Memory” error message. The memory must be cleared before another sample can be counted.

7.6.3 EDD Creation

1. When all samples and associated QC samples are completed, select the “Group Done” button on the iSolo.
2. In the laptop, open the iLink software.

3. Open iSoloEddGenerator.xlsx from desktop. If not present on laptop, download the most recent version from the FAL SharePoint server (Documents>Software>iSeries).
- NOTE:** only fields highlighted orange can be modified by users.
- a. Enable external Data Connections by clicking on the "Enable Content" yellow bar under tool ribbon.
 - b. Data Can be refreshed by navigating to Data Tab > Queries & Connections" > "Refresh All."
4. Select the "Input" Sheet and enter the ARF or batch number in the cell labeled "ARF Number." Enter number only.
 5. Enter the sample size from the ARF and select the appropriate units from the dropdown menu.
 6. Select the "EDD" tab in the workbook and review to ensure all data transferred correctly from the "Input" tab.
 7. Saving the EDD file
 - a. Open a new Workbook; data will be copied into the new Workbook.
 - b. Return to the iSoloEddGenerator and highlight all the cells that contain data and the column headers on the "EDD" tab.
 - c. Copy the information by using the <CTRL + C> button combination or by right clicking in the highlighted fields and selecting "Copy" from the menu of options.
 - d. Return to the new Workbook and select Cell 1 (cell "A1").
 - e. Paste the information by right clicking in the cell and selecting the option "Paste as value"; the button has a clipboard with "123" text in front of it.
 - f. Once the information is pasted, save the new Workbook as a CSV (Comma Delimited Format) file, as the name of the QC batch, in the laptop folder located in C:\HotSpot\iSOLO™\Completed\ReportCSVs.

7.7 Quality Control

- All alpha/beta standards in use are traceable to NIST or similar national standardizing body.
- Calibration of iSOLO™ is described in accordance with procedures documented in the *iSOLO™ Alpha/Beta Counting System User's Manual*.
- Instrument QC includes continuing background, alpha and beta efficiency calibration checks.
- Daily/Initial/Shift Field Performance Verification.
- Periodic Instrument Background Verification (1 per 20 samples and best done at the beginning of a batch).
- Control charts.

7.8 Calibration

To start the calibration process, press **SETUP** on the lower right side of the iSOLO™ front panel. See main screen prompt below:

Setup	
1	Delete Data
2	Set Security Level
3	Define Procedure
4	System Information
5	Setup Printer
6	Define Report
7	Define Std Sources
8	Detector Parameters
9	Calibrations
10	Quality Control
11	Set Date/Time
12	Define Users
13	Clear QC Log
14	Set Analysis Parm

Figure 7.12: iSOLO™ Setup Screen

NOTE: Do not change any setup parameter other than the calibration process described below unless reviewed by laboratory staff.

2. Using the arrow keys, position the cursor to #9 on the main screen.
3. Press **ENTER** and the following screen is displayed:

CALIBRATION	
1	Define Calibration
2	Execute Calibration

Figure 7.13: Calibration Screen

4. Define Calibration:
 - a. If you have no need to review these parameters, go to next section. Select **1, DEFINE CALIBRATION** and press **ENTER** if you want to review calibration parameters. Select **1, PRIMARY CALIBRATION**.
Press the **CANCEL** key to return to the **CALIBRATION** menu. **NOTE:** Do not make any changes unless reviewed by the Fly Away Laboratory Manager.
5. Execute Calibration:

Using the arrow keys, select **2 EXECUTE CALIBRATION** and press **ENTER**.

CALIBRATION	
1	Define Calibration
2	Execute Calibration

Figure 7.14: Calibration Execution Screen

- a. Using the arrow keys, move cursor to **2 PRIMARY CALIBRATION**, and press **ENTER**.

Select Calibration	
1	Primary Calibration
2	Field Calibration
3	Calibration 3
4	Calibration 4
5	etc....

Figure 7.15: Calibration Routine List Screen

6. Perform “Background Calibration” Measurements:

NOTE: Background calibrations should always be performed prior to efficiency calibrations as efficiency values are background corrected.

- a. Press **ENTER**, and the main screen is displayed:

Execute Calibration	
1	Background
2	α efficiency
3	β efficiency

Figure 7.16: Calibration Type Screen

- b. Select **1** and press **ENTER**, and the following screen is displayed:

CALIBRATION	
Insert BkgBlank Src	
Press Enter	

Figure 7.17: Blank Calibration Source Screen

- c. Locate the blank sample.
- d. Open sample drawer.
- e. Remove any existing sample.
- f. Load blank sample.
- g. Close the sample drawer.
- h. Press **ENTER**.
- i. Press **COUNT** on main front panel of iSOLO™.

- j. When count is complete, the following screen is displayed:

CAL PROCEDURE COMPLETE	
α Backgnd:	Cpm
β Backgnd:	Cpm
Press Enter to Accept	
Press Cancel to Reject	

Figure 7.18: Blank Calibration Acceptance Screen

- k. Press **ENTER** to accept.
7. Perform “Alpha Efficiency Calibration” Measurements:
- a. Using the arrow keys, select **2** and press **ENTER**.

Execute Calibration	
1	Background
2	α efficiency
3	β efficiency

Figure 7.19: Calibration Type Screen

- b. The following screen is displayed:

CALIBRATION	
Insert Am-50mm NT567 Src	
Press Enter	

Figure 7.20: Alpha Calibration Source Screen

- c. Locate the Am-241 standard assigned to the counter.
- d. Open sample drawer.
- e. Remove the blank sample.
- f. Load the Am-241 standard.
- g. Close the sample drawer.
- h. Press **ENTER**.
- i. Press **COUNT** on main front panel of iSOLO™.
- j. When count is complete, the following screen is displayed:

CAL PROCEDURE COMPLETE	
α Efficiency:	%
Press Enter to Accept	
Press Cancel to Reject	

Figure 7.21: Alpha Calibration Acceptance Screen

- k. Press **ENTER** to accept if in acceptable range.
8. Perform “Beta Efficiency Calibration” Measurements:
- a. Using the arrow keys, select **3** and press **ENTER**.

Execute Calibration	
1	Background
2	α efficiency
3	β efficiency

Figure 7.22: Calibration Type Screen

- b. The following screen is displayed:

CALIBRATION	
Insert Sr-50mm NT566 Src	
Press Enter	

Figure 7.23: Beta Calibration Source Screen

- c. Locate the Sr-90 standard assigned to the counter.
- d. Open Sample drawer.
- e. Remove the Am-241 standard.
- f. Load the Sr-90 standard.
- g. Close the sample drawer.
- h. Press **ENTER**.
- i. Press **COUNT** on main front panel of iSOLO™.
- j. When count is complete, the following screen is displayed:

CAL PROCEDURE COMPLETE	
β efficiency:	%
Press Enter to Accept	
Press Cancel to Reject	

Figure 7.24: Beta Calibration Acceptance Screen

- k. Press **ENTER** to accept if in acceptable range. The following screen is displayed:

Field Calibration Is Complete Press Any Key

Figure 7.25: Calibration Completion Screen

- l. Open sample drawer.
 - m. Remove the standard.
 - n. Close the sample drawer.
9. Print out System Parameters. See [Section 7.7, Reporting](#), for instruction on printing system reports. Below is the set of the iSOLO™ internal procedures:

Calibration Procedure (based upon 2" dia. sources)

- Name = "Primary/Field Calibration"
- Background Cal Parameters
 - Count time = 4 minutes
 - Repeat = 5 (20 minutes total background count time)
- Alpha Eff Cal Parameters
 - Count time = 1 minute
 - Repeat = 5 (5 minutes total count time)
 - Alpha source = "Am-50mm NT567"
- Beta Eff Cal Parameters
 - Count time = 1 minute
 - Repeat = 5 (5 minutes total count time)
 - Beta source = "Sr-50mm NT566"
- Total calibration procedure time = 30 minutes

QC Procedure (Daily/Periodic)

- Name = "Daily QC"
- Reference calibration = "Primary/Field Calibration"
- Daily Bkg Parameters
 - Count time = 4 minutes
 - Repeat = 1 (4 minutes total background count time)
 - Warning level = 2
 - Lockout level = OFF
- Daily Alpha Eff Parameters
 - Count time = 1 minute
 - Repeat = 1 (1 minute total count time)
 - Warning level = 2
 - Lockout level = OFF
- Daily Beta Eff Parameters
 - Count time = 1 minute
 - Repeat = 1 (1 minute total count time)
 - Warning level = 2
 - Lockout level = OFF
- Total QC procedure time = 7 minutes

#1-A Smear Screening Procedure – 1" Diameter Smears

- Name = "25mm 2 min dpm"
- Reference calibration = "Primary/Field Calibration"
- Unknown sample diameter = 25mm
- Report = "Sample Report"

- Count time = 2 minutes
- Sample repeat = 1
- Count presets = 100,000
- Activity units = “dpm”
- Action limits = n/a

#2-B Swipe Screening Procedure – 1.5” & 2” Diameter Samples

- Name = “47mm 2 min dpm”
- Reference calibration= “Primary/Field Calibration”
- Unknown sample diameter = 47mm
- Report = “Sample Report”
- Count time = 2 minutes
- Sample repeat = 1
- Count presets = 100,000
- Activity units = “dpm”
- Action limits = n/a
- [Primarily for swipe counting, but could also be used to screen air filters]

#3-C Smear Counting Procedure – 1” Diameter Samples

- Name = “25mm 10 min dpm”
- Reference calibration= “Primary/Field Calibration”
- Unknown sample diameter = 25mm
- Report = “Sample Report”
- Count time = 10 minutes
- Sample repeat = 1
- Count presets = 100,000
- Activity units = “dpm”
- Action limits = n/a
- [To be used for smears]

#4-D Swipe Counting Procedure – 1.5” & 2” Diameter Samples

- Name = “47mm 10 min dpm”
- Reference calibration= “Primary/Field Calibration”
- Unknown sample diameter = 47mm
- Report = “Sample Report”
- Count time = 10 minutes
- Sample repeat = 1
- Count presets = 100,000
- Activity units = “dpm”
- Action limits = n/a
- [To be used for swipes]

#5-E Air Filter Counting Procedure – 2” Diameter Sample

- Name = “47mm 10 min μCi ”
- Reference calibration= “Primary/Field Calibration”
- Unknown sample diameter = 47mm
- Report = “Sample Report”
- Count time = 10 minutes
- Sample repeat = 1
- Count presets = 100,000
- Activity units = “ μCi ”
- Action limits = n/a
- [To be used for 2" diameter air filters]

#6-F Air Filter Counting Procedure – 4” Diameter Sample

- Name = “100mm 10 min μCi ”
- Reference calibration= “Primary/Field Calibration”
- Unknown sample diameter = 60mm
- Report = “Sample Report”
- Count time = 10 minutes
- Sample repeat = 1
- Count presets = 100,000
- Activity units = “K user defined” [ccfv=1.3E-6, ccfs=1.3E-6, label = μCi]
- Action limits = n/a
- [To be used for 4" diameter air filters]

#7-G Extended Air Filter Counting Procedure – 2" Diameter Sample

- Name = “47mm 60 min μCi ”
- Reference calibration= “Primary/Field Calibration”
- Unknown sample diameter = 47mm
- Report = “Sample Report”
- Count time = 60 minutes
- Sample repeat = 1
- Count presets = 100,000
- Activity units = “ μCi ”
- Action limits = n/a
- [To be used for 2" diameter air filters]
- [Could also be used to provide enhanced results on smears]

#8-H Extended Air Filter Counting Procedure – 4" Diameter Sample

- Name = “100mm 60 min μCi ”
- Reference calibration= “Primary/Field Calibration”
- Unknown sample diameter = 60mm
- Report = “Sample Report”
- Count time = 60 minutes
- Sample repeat = 1
- Count presets = 100,000
- Activity units = “K user defined” [ccfv=1.3E-6, ccfs=1.3E-6, label = μCi]
- Action limits = n/a
- [To be used for 4" diameter air filters]
- [To be used for 4" diameter air filters]

7.9 References

iSOLO™ Alpha/Beta Counting System User's Manual

7.10 Document History

Johnson, Mark, *Hotspot iSOLO™ Low Background Alpha/Beta Counting Equipment*, 2006

Bibby R., Conrado C., Hume R., *Hotspot iSOLO™ Low Background Alpha/Beta Counting Equipment*, 2011

Bibby R., Conrado C., Hume R., Torretto P., *Hotspot iSOLO™ Low Background Alpha/Beta Counting Equipment*, 2012

Section 9. Analytical Balance Use

Table of Contents

9.1	Introduction	3
9.1.1	Scope and Application.....	3
9.1.2	Summary of Method	3
9.1.3	Responsibilities	3
9.2	Balance Setup	3
9.2.1	Safety/Environment/Precautions	3
9.2.2	Required Equipment	5
9.2.3	Installation Location and Requirements	5
9.2.4	Assembly	6
9.2.5	Conditioning the Balances	7
9.2.6	Leveling	7
9.2.7	Connecting to AC Power	7
9.2.8	Energizing/De-energizing	8
9.2.9	Calibration/Adjustment	8
9.3	Daily Linearity, Reproducibility, and Accuracy Checks	10
9.3.1	Linearity Checks	10
9.3.2	Reproducibility Checks	11
9.3.3	Accuracy Checks	13
9.3.4	Action for Linearity, Reproducibility or Accuracy Check Failure	13
9.4	Procedure.....	13
9.4.1	Weighing Samples.....	13
9.4.2	Taring	14
9.5	Preparation for Transport.....	14
9.5.1	Preparation of Balances for Transport.....	15
9.5.2	Preparation of Weights for Transport.....	15
9.6	Maintenance	15
9.6.1	Annual Calibration and Preventative Maintenance of Balances.....	15
9.6.2	Annual Calibration of Weights	16
9.6.3	Safety Inspection.....	16
9.6.4	Balance Cleaning	16
9.7	Records	17
9.7.1	Calibration /Adjustment Log	17
9.7.2	Daily Linearity and Accuracy Checks Log.....	17
9.7.3	Weekly Reproducibility Check Log	17
9.8	Balance Specifications.....	17

Tables

Table 9.1: Weights for Linearity Check 11
Table 9.2: Weights for Reproducibility Check 12
Table 9.3: Balance Specifications 17

9.1 Introduction

The Fly Away Laboratory maintains three top-loading precision balances for the purpose of weighing analytical samples in the field. Limiting weight capacity is 6,200 g, and limit of accuracy is 0.001g (0g-500g range). All balances and weights are calibrated annually by a certified vendor. Preventative maintenance service is performed at the time of calibration. Annual calibration and routine check records are located in the designated binder for each balance.

9.1.1 Scope and Application

This procedure describes the steps to set up the Fly Away Laboratory balances, perform and document quality assurance (QA) checks, deal with failure of QA checks, measure samples, and prepare the balances for transport and storage. In addition to the annual calibration and preventative maintenance services, linearity and accuracy checks are performed daily prior to operation on all balances. A reproducibility check is performed weekly.

9.1.2 Summary of Method

Upon setup, a calibration/adjustment and a complete set of accuracy, linearity, and reproducibility checks are performed for each balance and tolerance range(s). Daily prior to measurements, linearity checks, and an accuracy check for each measurement process are performed using the closest certified calibration weight(s). Following initial setup, reproducibility checks are performed weekly.

9.1.3 Responsibilities

Annual calibrations and preventative maintenance are performed by a certified outside vendor. The vendor completes the service, updates the calibration stickers, and provides a calibration certificate for each balance and the weight set.

Fly Away Laboratory personnel are responsible for initial setup of the balances, plus performance and documentation of initial quality assurance checks. In conjunction with the weighing of samples and properly documenting the results, laboratory personnel are responsible for performing and documenting routine quality assurance checks for each balance. With termination of the deployment, Fly Away Laboratory personnel are then responsible for safely preparing the balances for transport.

9.2 Balance Setup

9.2.1 Safety/Environment/Precautions

Safety

- Care should be taken when lifting heavy weights to avoid personal injuries.
- The balances are not allowed to be used in hazardous areas/locations because they do not have EX approval certificates certifying them as electrical apparatuses for potentially explosive atmospheres (Certificate of Conformity).

Environment

In order to pass any test of reproducibility, an instrument must be operating in an acceptable environment. A poor environment degrades the results of a standard deviation (SD) test and falsely suggests that the performance is substandard. There are several aspects of the environment that impact the performance of a laboratory balance. Do not expose balances unnecessarily to:

- Extreme temperatures - The accuracy and overall performance of any laboratory balance is affected by the room temperature. For best stability and performance, the room temperature should be regulated to within one degree Fahrenheit without interruption. The instrument should remain with power ON continuously.
 - Allowable storage temperature: -40°C to $+70^{\circ}\text{C}$ (-40°F to $+158^{\circ}\text{F}$)
 - Allowable operating ambient temperature range is 0° to 40°C (32° to 104°F)
- Moisture - Do not expose balances to extreme moisture over longer periods. Moisture in the air can condense on the surfaces of balance whenever a cold balance is brought to a substantially warmer place. If you need to transfer a balance to a warmer area, make sure to condition it for about two hours at room temperature.
- Shocks, Blows, or Vibrations - Many laboratory balances are extremely sensitive to vibration or movement. If the weight readings change as you walk around the instrument, or if the readings change as you lean on the table or move objects on the table, then the table and floor are affecting weight readings. You can minimize these effects by using an especially sturdy table and minimizing movement. Users of microbalances often need specially built marble tables on concrete floors.
- Air Drafts – In the cases of measurements with resolution of .001 gram and less, the force exerted by moving air is readily detectable. A shroud or enclosure around the weighing pan will shield the pan from these effects. Avoid plastic materials for draft shields.
- Static Electricity - Static electricity exerts a mechanical force that is readily detectable by analytical and microbalances. An example of static electricity exerting a mechanical force would be lint sticking to clothing. Static will be a problem when it exists on the object being weighed, on the person using the balance, on draft shields, or on weighing vessels. Sources of static are carpets, Vibram shoe soles, plastic draft shields, plastic weighing vessels, and melamine (Formica) table tops. Low ambient humidity exacerbates static problems.
 - You can test for a static problem easily. On an analytical balance place a metal enclosure (a coffee can works well) over the weighing pan, so that the pan is enclosed by the can but NOT touched by it. If the weight readings stabilize with the can in place, then static may be the cause of the instability.
 - Notice that the coffee can will provide an effective draft shield too.

General Precautions - Handling Test Weights

The weights used to test laboratory balances are precision devices and need to be handled accordingly. When handling weights, avoid direct hand contact with weights by using clean gloves or special lifting tools. Also, avoid sliding weights across any surface, especially across the stainless steel weighing pan of the balance under test. If a weight is dirty, carefully dust it to

remove any foreign matter. If a weight is damaged, remove it from service and use another certified weight.

9.2.2 Required Equipment

Balances

- Sartorius CPA1003P [0-500 g, 0.001 g readability / 500-1,010 g, 0.01 g readability], with weighing pan, pan support, base plate, and AC adapter.
- Analytical draft shield for CP1003P, with cover.
- Sartorius CPA6202P [0-500 g, 0.01 g readability / 0-3,000 g, 0.02 g readability / 0-6,200 g, 0.05 g readability], with weighing pan and AC adapter.

Calibrated Weight Set

- 3 each 2 kg class 1 NIST-traceable electronic balance weights
- 2 each 1 kg class 1 NIST-traceable electronic balance weights
- 2 each 500 g class 1 NIST-traceable electronic balance weights
- 2 each 200 g class 1 NIST-traceable electronic balance weights
- 1 each 100 g class 1 NIST-traceable electronic balance weights

Supplies and associated equipment

- Dusting brush
- Gloves (cotton, surgical or nitrile)
- Wipes (lint-free cloth, Kim wipes, or similar material)
- Level (bubble)
- Thermometer
- Balance binder(s) [one for each balance]
 - Balance Manufacturer's Operating Manual
 - Balance Calibration Certificates
 - Calibration/Adjustment logsheets
 - Daily Linearity, and Accuracy check logsheets
 - Weekly Reproducibility check logsheets
- Weight Set Binder
 - Weight Calibration Certificates
- Stainless steel wipes
- Mini-vac with hose extension

9.2.3 Installation Location and Requirements

After unpacking the balances and associated components, check each immediately for any visible damage as a result of rough handling during shipment. If this is the case, proceed as directed in [Section 9.6.3, Safety Inspection](#).

Choose a location that is not subject to the following negative influences:

- Heat (heater or direct sunlight)
- Drafts from open windows and doors

- Extreme vibrations during weighing
- Excessive moisture


Allowable operating ambient temperature range is 0° to 40°C (32° to 104°F)

Refer to the Environment subsection of [Section 9.2.1, Safety/Environment/Precautions](#), for more information.

9.2.4 Assembly


PT3100 and CPA6202P

1. Remove balance from its case. Be sure to lift from the sides or bottom, and not to grab from the balance top.
 - a. Place the balance on a flat, level surface.
 - b. Place the weighing pan on the balance.



CPA1003P

1. Remove balance from its case. Be sure to lift from the sides or bottom, and not to grab from the balance top.
2. Place the balance on a flat, level surface.
3. Check the sliding lock device on the back of the draft shield. Make sure it is in the “open” position (to the right).
4. Position the draft shield carefully on the balance.
5. Secure the draft shield by pressing lightly on the draft shield base and moving the sliding lock to the left.
6. Place components inside the chamber in the following order:
 - a. Base plate
 - b. Shield ring
 - c. Pan support
 - d. Weighing pan



9.2.5 Conditioning the Balances

Moisture in the air can condense on the surfaces of a cold balance whenever it is brought into a substantially warmer place. Upon initial setup or if you transfer a balance to a warmer area, make sure to condition it for about 2 hours at room temperature, leaving it unplugged from AC power.

9.2.6 Leveling


Purpose: To compensate for unevenness at the place of installation.

PT3100

1. The PT3100 balance lacks a built-in level and adjustable feet.
10. Using a bubble level on the balance pan, shim the front balance feet (or table feet) to level the balance.

CPA1003P and CPA6202P

1. Only the 2 front feet are adjusted to level the balance; the level indicator is at the rear of the balance.
2. Extend the two rear feet.
3. Turn the 2 front feet until the air bubble is centered within the circle of the level indicator.



9.2.7 Connecting to AC Power

1. Connect the angle plug to the balance/scale.
2. Connect the power cord to the AC adapter.

3. Plug the power cord into the wall outlet.

9.2.8 Energizing/De-energizing

To turn the balance on and off, press the  key (PT3100) or  key (CPA1003P and CPA6202P).

- Self test - After the power has been turned on, a test of all essential electronic functions (PT3100 only) and/or the display is run automatically.
- Warm up - To deliver exact results, the balance must warm-up for at least 30 minutes after initial connection to AC power. Only after this time will the balance have reached the required operating temperature.

9.2.9 Calibration/Adjustment

Adjust the balance after setting it up at the place of use.

Purpose

Calibration is the determination of the difference between the weight readout and the true weight (mass) of a sample. Calibration does not entail making any changes within the balance.

Adjustment is the correction of any difference between the measured value displayed and the true weight (mass) of the sample, or the reduction of the difference to an allowable level within the maximum permissible error limits.

Features

Calibration/adjustment can be performed only when:

- There is no load on the balance,
- The balance is tarred, and
- The internal signal is stable.

NOTE: The menu code setting **193** must be selected in the Setup menu (refer to manufacturer operating instructions in balance notebook).

Initial Conditions

Before proceeding, ensure that the balance:

- Has been allowed to warm-up for at least 30 minutes
- Is level
- Is free of any load or debris
- Has been tarred ([See Section 9.4.2, Taring](#)).

9.2.9.1 Calibration/Adjustment for CPA1003P and CPA6202P

[Manufacturer Operating Manual, pages 20-21; balance logbook]

Inside the balance housing is a motorized calibration weight which is applied and removed automatically for internal calibration. To activate calibration, press (CAL):

- The built-in calibration weight is applied automatically.
- The balance is calibrated.
- If configured for **CALIBRATE THEN AUTO ADJUST IN ONE OPERATION** is selected in Setup menu (1 10 1; factory setting), the balance is now adjusted automatically.
- The internal calibration weight is removed.

NOTE: In the Setup menu, you can configure whether:

- Calibration is always followed automatically by adjustment (1 10 1), or
- You have the choice of ending the sequence or starting adjustment after Calibration (1 10 2). If no difference is determined between nominal and actual weights, you can end the calibration/adjustment routine following calibration. Two keys are active at the point:
 - (CAL) = start calibration/adjustment
 - (CF) = end the sequence

9.2.9.2 *Adjustment/Calibration for PT3100*

[Manufacturer Operating Manual, page 8; balance logbook]

The PT3100 balance does not have an internal, automatic calibration/adjustment feature; this function is performed using a single, external, calibrated 1,000 g weight.


1. Identify and obtain the appropriate certified test weight for the balance to be tested.
 - a. For the PT3100 balance, with a single-range of 0-3,100 g, use 1 each 1 kg weight.
 - b. Certified test weights with an expired calibration and/or certification shall be labeled conspicuously on the exterior case “Do Not Use,” and shall be removed from further service. Notify the Laboratory Test Lead and ensure that, when possible, the weight is calibrated (See [Section 9.6.2, Annual Calibration of Weights](#)).
 - c. Wearing gloves, examine the test weight for cleanliness and damage (e.g., nicks, scratches, etc.). As needed, carefully dust the certified test weight with a dry, lint-free cloth to remove any foreign matter. If damage is found, clearly note on the exterior case “Do Not Use,” and remove the weight from further service. Notify the Laboratory Test Lead and ensure that, when possible, the weight is repaired (if feasible – or replaced), re-certified, and calibrated (See [Section 9.6.2, Annual Calibration of Weights](#)).

During calibration with a calibration weight, the sensitivity of the balance is adjusted to changes in ambient conditions.

11. Remove the protective cap located on the front right of the balance and slide the access switch (6) in the direction of the arrow




12. With the balance turned off, hold down the **F1** key and briefly press the **power** key.




Upon completion of the automatic self-test, release the **F1** key as soon as the “C” is displayed (upper right corner of display).

13. Unload the balance and press the tare control (7) to zero the display.



14. When the display shows a zero readout, press the **F1** key. “CAL” and the calibration weight readout will now be displayed.



15. Center the 1,000 g calibration weight on the weighing pan, and then the balance self-calibrates automatically. The end of the calibration/adjustment is indicated by the weight unit symbol that appears on the display.
16. Relock the calibration access function by sliding the access switch back to its original setting (to the left), and replace the protective cap.



17. After calibration, use the **Power** key to turn the balance off and then on again so that you have direct access again to the weighing mode.

9.3 Daily Linearity, Reproducibility, and Accuracy Checks

9.3.1 Linearity Checks

Linearity testing verifies the accuracy of the instrument at intermediate values of weight. The balance linearity test measures the ability of the balance to accurately measure an added weight before and after a non-measured weight load has been placed on the balance. Prior to operation, on a daily basis, follow the Linearity Check procedure outlined below. Record results on the

“Daily Linearity Check Log” record sheet (see [Section 9.7.2, Daily Linearity and Accuracy Checks Log](#)).

The procedure is as follows:

1. Identify and obtain the appropriate certified test weights for the balance to be tested (see Table 9.1). Use two sets of weights, each of approximately one-half the weighing capacity of the balance. It is imperative that these two weights not be interchanged within this procedure. These two weights are referred to as “weight A” and “weight B.”

Table 9.1: Weights for Linearity Check

Weight Range	PT3100	CPA6202P	CPA1003P
0 – 3100 g	1 kg + 500 g		
0 – 3000 g		1 kg + 500 g	
3000 – 6200 g		2 x 2 kg	
0 – 500 g			200 g
500 – 1010 g			500 g + 200 g

- a. Certified test weights with an expired calibration and/or certification shall be labeled conspicuously on the exterior case “Do Not Use” and shall be removed from further service. Notify the Laboratory Test Lead and ensure that, when possible, the weight is calibrated (See [Section 9.6.2, Annual Calibration of Weights](#)).
 - b. Wearing gloves, examine the test weight for cleanliness and damage (e.g., nicks, scratches, etc.). As needed, carefully dust the certified test weight with a dry, lint-free cloth to remove any foreign matter. If damage is found, clearly note on the exterior case “Do Not Use,” and remove the weight from further service. Notify the Laboratory Test Lead and ensure that, when possible, the weight is repaired (if feasible, or replaced), re-certified, and calibrated (See [Section 9.6.2, Annual Calibration of Weights](#)).
- 18.
 19. Re-zero (tare) the display. Place “A” on the pan (at the center) and record the reading on the “Linearity Chart” in the column marked “0% - 50%.”
 20. Remove “A” and place “B” on the pan (at the center). Re-zero (tare) the display with “B” still on the pan. Again place “A” on the pan, with “B” still on the pan. Record the reading under the column marked “50% - 100%.” Calculate the difference between the two (0%-50% & 50%-100%) readings. The difference should be less than the linearity tolerances for each balance and range:
 - PT3100: ± 0.2 g
 - CPA6202P, 0-3,000 g: ± 0.02 g / 3,000-6,200 g: ± 0.05 g
 - CPA1003P, 0-500 g: ± 0.001 g / 500-1,010 g: ± 0.01 g

9.3.2 Reproducibility Checks

Reproducibility testing entails repeatedly weighing a given object, recording the results, and analyzing those results. Prior to operation, on a daily basis, follow the Linearity Check procedure outlined below. A test weight equal to, or nearly equal to, the weighing capacity of the instrument should be selected.

Twenty pairs of readings should be taken for 2 data sets: “full-scale reading” and “zero reading.” Record results on the Daily Reproducibility Check Log record sheet (see [Section 9.7.3, Weekly Reproducibility Check Log](#)).

A detailed procedure is as follows:

1. Identify and obtain the appropriate certified test weights for the balance to be tested (see Table 9.2).

Table 9.2: Weights for Reproducibility Check

Weight Range	PT3100	CPA6202P	CPA1003P
0 – 3100 g	2 kg, 1 kg		
0 – 3000 g		2 kg, 1 kg	
3000 – 6200 g		3 x 2 kg	
0 – 500 g			500 g
500 – 1010 g			1 kg

- a. Certified test weights with an expired calibration and/or certification shall be labeled conspicuously on the exterior case “Do Not Use” and shall be removed from further service. Notify the Laboratory Test Lead and ensure that, when possible, the weight is calibrated (See [Section 9.6.2, Annual Calibration of Weights](#)).
 - b. Wearing gloves, examine the test weight for cleanliness and damage (e.g., nicks, scratches, etc.). As needed, carefully dust the certified test weight with a dry, lint-free cloth to remove any foreign matter. If damage is found, clearly note on the exterior case “Do Not Use,” and remove the weight from further service. Notify the Laboratory Test Lead and ensure that, when possible, the weight is repaired (if feasible, or replaced), re-certified, and calibrated (See [Section 9.6.2, Annual Calibration of Weights](#)).
2. Tare the instrument to read all zeros. Do not record the initial zero reading.
 3. Place the test weight on the pan. Record the reading in the column labeled “FULL SCALE READING.”
 4. Remove the weight (do not rezero), and record the reading under “ZERO READING.”
 5. Repeat steps 2 and 3 until lines 1 through 10 are all filled in.
 6. Transcribe the 2 columns of numbers into the Reproducibility Check spreadsheet.
 7. Use the Reproducibility Check spreadsheet to calculate the standard deviation and coefficient of variation (CV) of both columns of numbers.
 8. Calculated standard deviations larger than allowed in the instrument specifications indicate that the instrument is either operating in an unstable environment (static, air draft, warm-up, vibration, etc.), or that the instrument is in need of repair:
 - PT3100: ± 0.1 g
 - CPA6202P, 0-3,000 g: ± 0.01 g / 3,000-6,200 g: ± 0.03 g
 - CPA1003P, 0-500 g: ± 0.001 g / 500-1,010 g: ± 0.01 g

9.3.3 Accuracy Checks

Prior to each measurement process, on a daily basis, verify balance accuracy for a target sample. This verification is performed using the closest estimated certified weight as follows:

1. Identify and obtain the appropriate balance binder/log for the balance to be used.
2. Check the calibration sticker on the balance and weight set to ensure the calibration is current.
3. Clean the balance pan and weighing chamber of residual dust and drippings.
4. Check the balance level indicator. The bubble should be within the black outlined circle. Readjust the leveling feet if necessary.
5. Zero the balance by pressing the tare bar.
6. Place the required certified weight (the closest to the estimated weight to be measured) on the balance pan. Wait for the balance to be stabilized and record the result in the balance logbook. Remove the weight from the balance pan.
7. The allowable control limit is $\pm 0.1\%$ of the certified weight value across the entire weight range. Notify the Laboratory Team Lead if the balance fails to pass the accuracy test. Place a conspicuous “Out of Order” sign on the balance and follow the procedures outlined in [Section 9.2.9, Calibration/Adjustment](#).

9.3.4 Action for Linearity, Reproducibility or Accuracy Check Failure

1. Perform a calibration/adjustment on the balance (see [Section 9.2.9, Calibration/Adjustment](#)) if daily linearity, reproducibility, or accuracy checks fail.
2. Repeat linearity, reproducibility, and accuracy checks if a calibration/adjustment is performed.
3. If the balance continues to fail linearity, reproducibility, or accuracy checks, remove the balance from service.

9.4 Procedure

9.4.1 Weighing Samples

Refer to the balance manufacturer’s operating instructions for specific procedures on the proper operating techniques unique to that particular balance.

9.4.1.1 CPA1003P with Draft Shield

To weigh an unknown:

1. Verify successful completion of operational accuracy check for balance/measurement process.
2. Clean the balance pan and weighing chamber of residual dust and drippings.
3. Check the balance level indicator. The bubble should be within the black outlined circle. Readjust the leveling feet if necessary.
4. Ensure that the glass doors of the weighing chamber are completely closed.
5. Turn the display on and carefully watch the automatic digital readout demonstration.

6. If any segment fails to light during the readout demonstration, place an “Out of Order” sign on the balance, and follow the procedures outlined in [Section 9.2.9, Calibration/Adjustment](#).
7. Zero the balance by pressing the tare bar.
8. Display subsequently indicates zero (weighing mode). The number of decimal places depends on the readability of the balance as well as the selected weighing range. The balance is now ready to weigh an unknown.
9. Open a door on the weighing chamber and carefully place the unknown on the balance pan.
10. Close the weighing chamber door.
11. Wait for stability and read the results.

9.4.1.2 Top-Loading Balance

To weigh an unknown:

1. Verify successful completion of operational accuracy check for balance/measurement process.
2. Clean the balance pan of residual dust and drippings.
3. Check the balance level indicator. The bubble should be within the black outlined circle. Readjust the leveling feet if necessary.
4. Turn the display on by briefly pressing the control/tare bar.
5. If any segment fails to light during the readout demonstration, place an “Out of Order” sign on the balance, and follow the procedures outlined in [Section 9.2.9, Calibration/Adjustment](#).
6. Zero the balance by pressing the tare bar.
7. Display subsequently indicates zero (weighing mode). The number of display digits depends on the readability of the balance as well as the selected weighing range. The balance is now ready to weigh an unknown.
8. Carefully place the unknown on the balance pan.
9. Wait for the stability and record the result.

9.4.2 Taring

To tare an item:

1. Place the container on the balance pan.
2. Briefly press the tare bar.
3. The container has now been tared. The weighing range minus the tare weight is now available for weighing.

9.5 Preparation for Transport

Care must be taken in preparing the balances, weights, and associated components for transport to ensure they will be operationally ready for subsequent deployments.

9.5.1 Preparation of Balances for Transport

To prepare a balance for transport:

1. De-energize balance (See [Section 9.2.8, Energizing/De-energizing](#)).
2. Disconnect power cord and AC adapter.
3. Clean balance (all) and draft shield (CPA1003P) (See [Section 9.6.4, Balance Cleaning](#)).
4. Before disassembling and packing balances and associated components, check each immediately for any visible damage as a result of mishaps during weighing operations. If this is the case, proceed as directed in [Section 9.6.3, Safety Inspection](#).
5. Disassemble each balance by reversing the processes covered in [Section 9.2.4, Assembly](#).
6. Carefully re-pack each balance and associated components back into their transport cases. Be sure to handle the balances only from the sides or base; do not grab the sensitive component area on top of the balance.

9.5.2 Preparation of Weights for Transport

Care must be taken in preparing the balances, weights, and associated components for transport to ensure they will be operationally ready for subsequent deployments. Improper storage and/or prolonged contact with moisture, fingerprints, or other foreign matter may damage or invalidate the calibration of the weights.

To prepare certified weights for transport:

1. Inspect each weight for any visible damage. If any is found, remove it from service and make note of this in the Annual Calibration and Maintenance Log (see [Section 9.6.1, Annual Calibration and Maintenance of Balances](#)). When possible, have the weight serviced by trained personnel. If the damage is excessive, the weight needs to be replaced.
2. Wearing gloves, wipe each weight with a clean, dry cloth.
3. Place each weight into its individual storage case; then, place each storage case into the weight set transport case.

9.6 Maintenance

9.6.1 Annual Calibration and Preventative Maintenance of Balances

1. On an annual basis, ensure that preventative maintenance and calibration is performed for each balance by a certified vendor.
2. Upon completion of the annual preventative maintenance and calibration, inspect each balance (see [Section 9.6.3, Safety Inspection](#)) and then verify calibration certificate and stickers.
3. Place the new calibration certificate in the associated balance binder.

9.6.2 Annual Calibration of Weights

1. On an annual basis, ensure that preventative maintenance and calibration is performed for each weight by a certified vendor.
2. Upon completion of the annual preventative maintenance and calibration, inspect each weight and then verify calibration certificate and stickers.
3. Place the new calibration certificate in the certified weight set binder.

9.6.3 Safety Inspection

If there is any indication that safe operation of the balance is no longer warranted:

1. Turn off the power and disconnect the equipment from AC power immediately.
2. Label the equipment as out-of-service and lock it in a secure place to ensure that it cannot be used until the safety issue has been resolved. Notify the Fly Away Laboratory Manager .
3. When possible, have the equipment repaired by trained service technicians.

9.6.4 Balance Cleaning

Cleaning the Balance Housing

1. Unplug the AC adapter from the wall outlet.
2. Clean the balance using a piece of cloth that has been wetted with a mild detergent (soap) solution.
 - c. Make sure that no liquid or other foreign objects or dust (powder) enters the balance housing.
 - d. Do not use any aggressive cleaning agents (solvents or similar agents).
21. After cleaning, wipe down the balance with a soft, dry cloth.

Cleaning Stainless Steel Surfaces

1. Clean all stainless steel parts regularly.
2. Remove the stainless steel weighing pan and thoroughly clean it separately.
3. Use a damp cloth or sponge to clean any stainless steel parts on the balance by wiping them down. You can use any commercially available household cleaning agent that is suitable for use on stainless steel. Then wipe down the equipment to rinse thoroughly, making sure to remove all residues.
4. Afterwards, allow the balance to dry.
5. If desired, you can apply oil to the cleaned stainless steel surfaces as additional protection. Solvents are permitted for use only on stainless steel parts.

Cleaning the Weighing Chamber and Draft Shield

1. Open the draft shield cover and take out the removable parts.
2. Use a hand-held vacuum cleaner and mini-hose to remove any powdered sample material carefully.
3. Use blotting paper to remove any liquid sample material.

9.7 Records

9.7.1 Calibration /Adjustment Log

- PT3100
- CPA1003P
- CPA 62002P

9.7.2 Daily Linearity and Accuracy Checks Log

- PT3100
- CPA1003P
- CPA 62002P

9.7.3 Weekly Reproducibility Check Log

- PT3100
- CPA1003P
- CPA 62002P

9.8 Balance Specifications

Table 9.3: Balance Specifications

Manufacturer Series Model	Sartorius Portable PT3100	Sartorius CP CPA1003P	Sartorius CP CPA6202P
Weighing Capacity g	3,100	500/1,010	1,500/3,000/6,200
Readability g	0.1	0.001/0.01	0.01/0.02/0.05
Tare Range (by subtraction) g	-3,100	-1,010	-6,200
Repeatability, Standard Deviation $\leq \pm g$	0.1	0.001/0.01	0.01/0.01/0.03
Maximum Linearity $\leq \pm g$	0.2	0.002/0.02	0.02/0.02/0.05
Response time (average) s	1.5	≤ 2	≤ 1.5
Display update at stability (depends on the filter level selected) s	0.1; 0.2; 0.4	**	**
Display update when load on pan changes s	0.1	**	**
Adaptation to operating requirements and ambient conditions	By selection of 1 of 3 optimized filter levels	**	**
Stability range d	0.25...32 (selectable)	**	**
Operating temperature range °C	**	10° to 30° (50° to 86°F)	10° to 30° (50° to 86°F)
Allowable operating ambient temperature	273-313 K (0°C...+40°C)	0° to 40°C (32° to 104°F)	0° to 40°C (32° to 104°F)
Allowable relative humidity %	15...85 (non-condensing)	**	**
Sensitivity Drift within +10 to +30°C	1.5E-05 /°C	$\leq \pm 2E-06 /K$	$\leq \pm 2E-06 /K$

Manufacturer Series Model	Sartorius Portable PT3100	Sartorius CP CPA1003P	Sartorius CP CPA6202P
External calibration weight (of at least accuracy class...) g	**	1,000 (E2)	5,000 (F1)
Weighing pan size mm Weighing pan area cm	174x133 231	110 (inner dia.) 120	190x204 388
Weighing chamber height (weighing pan to draft shield cover) mm	**	240	**
Balance housing (WxDxH) mm	185x215x55	213x342x340	213x342x88
Net weight, approx. kg	1.2	6.5	4.7
AC power requirements V~	115 V, 50-60 Hz	AC adapter STNG6, 230 V or 115 V, 48-60Hz	AC adapter STNG6, 230 V or 115 V, 48-60Hz
Allowable voltage fluctuation	-20%...+15%	-20%...+15%	-20%...+15%

This page is intentionally left blank

Section 10: Data Handling and Verification/Validation

1. Review the final report against the analysis request form for the following information:
 - Sample ID Numbers
 - Customer Name
 - Sample Type
 - Sample Description
 - Sample Aliquot
 - Sample Units
 - Sample Date/Time
 - ARF Number
 - Count Time
 - Sample Geometry
 - Unidentified Peak Report (if applicable)
 - Appropriate Gamma Library
 - Analytical Method (e.g. LSC, GPC or Gamma)
 - Analyst ID
 - Comments

2. Next perform a technical review of the final report.
 - Once the report is reviewed and acceptable, sign and date the report.
 - Check the final report against the Electronic Data Deliverable (EDD).
 - Provide the entire package to the FAL Manager for final review.
 - Once the FAL Manager approves the data, forward a hardcopy along with the EDD to the customer.

This page is intentionally left blank

Appendix A: iSOCS™ Geometry Composer Tutorial

Introduction

A wide variety of sample configurations are analyzed with portable gamma spectral systems such as the FALCON™ 5000. Qualitative analysis results can be quantified by utilizing the CANBERRA ISOCS™ code in conjunction with the standard ISOCS™ and/or LabSOCS™ geometry templates. Efficiency calibration files can be created for specific counting scenarios. Below is a step by step job aid that will enable the laboratory staff to model a counting geometry and obtain qualitative analysis results.

Procedure

1. You must use an ISOCS™ CALIBRATED DETECTOR for analysis!!!
2. In the *Canberra ISOCS/LabSOCS™ Manual*, choose the geometry template that best suits the shape or geometry of the sample being analyzed.
3. Open the Geometry Composer from the Genie2000 folder on the desktop: select **FILE**→**OPEN** and select the appropriate template.


NOTE: If you are using a pre-defined geometry, press the edit dimensions button to “edit dimensions” of the geometry.

Below is an example of the template provided in the ISOCS™ program that allows you to input material and source dimensions. Based on the drawing, input the proper dimensions and materials here. Be mindful of units.

No.	Description	d.1	d.2	d.3	Material	Density	Rel.
1	Liner - side	2	79	67	acrylic	1.17	
2	Liner - end	2			acrylic	1.17	
3	Source - side	14			e&z smar	1.76	1.00
4	Source - end	21			e&z smar	1.76	1.00
5	Source - Detector	82.5	0				

If a material that matches (or is very close to) the material being analyzed is not listed in the pull-down menu, the “mu editor” can be used to create new materials in the library.

Below is an example of the “mu editor” window.



If the elemental mass ratios are known for the material, it can be defined by using the element selection box to the left. The atomic ratios of each molecule can be input using the “n =” selection box. For example: Water consists of two hydrogen atoms attached to one oxygen atom. To enter this, select **H** from the box, increase “n =” so that it equals 2, and then push the up arrow. To add the oxygen, select **O** from the list, change “n=” to 1, and then press the up arrow. If the matrix consists only of water, then the mass percentage would be 100. If there was salt in the water, then the mass ratio would have to be calculated and the salt would have to be added separately.

Alternatively, you can make a new substance by combining any ratio of the materials in the library using the utility at the right of the screen.

Once the new material is listed in the center box and the “Component Balance” is equal to 0, you must enter the mass density of the material, give it a name, and enter an optional comment to help identify the material. By clicking the **SAVE INTO LIBRARY** button, the new material is saved to the library and can be used in any future models.

- a. Once the correct dimensions and materials have been selected, the efficiency codes are ready to be executed.




- b. Check geometry validity by pressing this button: . This utility checks the geometrical parameters to make sure that a logical model has been created. Error messages are usually self-explanatory, and you will be able to figure out how to fix the problem. For errors that are not easily understood, refer to the *Canberra ISOCS™ Manual*.



- c. Modify or load energy list by pressing this button: 

Below is an example of the utility that allows you to modify the energy list. With this utility, you can choose the energies for which the code will calculate efficiencies. For most applications, the default energy list is adequate.

A rule of thumb is to be sure that there are at least 10 data points and that both the lowest and highest gamma energy of all the nuclides of interest are within the bounds of the energies selected. Just like the mu editor, the energy list can be saved and loaded into future models.



- d. Save the model with a name similar to 03_FAL_geoname replacing *geoname* with a descriptive name of the geometry and 03 with the detector number. Save the file in C:\GENIE2K\isocs\data\GEOMETRY folder. **Take note of where you saved the file.**
 - e. To run the efficiency calculator press the following button: 
 - f. Select **FILE** → **PRINT** to print out the geometry report. Retain this as part of the record.
4. To use the newly developed efficiency curve, open GENIE2K.
 - a. Open Gamma Acquisition & Analysis (from the Genie 2000 folder on the desktop).
 - b. **FILE** → **OPEN DATA SOURCE:** Select the CNF. File of the spectrum that is to be analyzed with the iSOCS™ geometry.
 - c. Select **CALIBRATE** → **EFFICIENCY** → **BY LABSOCS/ISOCS...**
 - d. Select the model that was just performed (.ecc file) **Geometry Composer**.
 - e. Select **NEXT** >.
 - f. Select **EFFICIENCY** unless instructed otherwise.
 - g. Select **NEXT** >.
 - h. Select **SHOW...**

- i. Select **LINEAR** as the curve type unless instructed otherwise. Ensure that all of the datapoints lie very close to the calculated curve fit. Print the chart in both linear and log scales and attach this to the geometry composer report. If a point needs to be dropped from the fit, select **LIST PKs...** and drop points as necessary. When satisfied with the fit, select **PRINT** for both the Log and Linear Scale. Select **OK** to commit the calibration to the file.
- j. Select **REPORT...** Print this report, and attach it to the geometry composer report and the graphs of the efficiency curve.
- k. **STORE** the calibration. Be sure to include information in the filename that points to what detector and geometry it pertains to. Be sure that the first character in the filename matches the detector number for which the model was created. For example, if a water cube was modeled on FAL03, then the filename should read something similar to “3waterbox.CAL.”
- l. Select **FINISH**.
- m. Associate the calibration with γ RATS by launching the program and expanding the **NON-ROUTINE** section at the bottom of the window. Select the desired model, enter a name for the geometry (needs to match the name of the *geoname* created earlier). Press **SET CALIBRATION**.
- n. Assemble the iSOCS™ report, the efficiency calibration report, the calibration graphs and attach to the Gamma Spectroscopy ISOCS Calibration cover sheet found in Appendix B.
- o. Fill out the Gamma Spectroscopy ISOCS Calibration cover sheet with the detector ID, the .CAL and the .GEO Calibration file names, and the date the model was created. Record the sample matrix (e.g. Soil, water, etc.) the degree of fullness, and any other description of the contents that is pertinent to the model. Make a detailed sketch of the geometry including all the pertinent dimensions. Sign and date the Modeled by field.

NOTE: The degree of fullness field is for any indication of sample quantity. It can be sample fill height, percent full, volume, etc.

- p. Have the calibration packet reviewed by another experienced gamma spectroscopist for completeness and correctness. File with the other calibration reports.

Appendix B: Fly Away Laboratory Forms

This page is intentionally left blank

**PORTABLE GAMMA SPECTROSCOPY
CALIBRATION**

Detector ID: _____

Manufacturer and Serial No.: _____

Archive File Names: _____

Source IDs: _____

Calibration Date: _____

CHECK LIST

All Calibration Packages shall include the following items:

- Peak Search Results Energy and Shape Calibration
- Energy and FWHM Report and Graphs
- Peak Search Results Efficiency Calibrations
- Efficiency Calibration Reports and Graphs
- Source Certificates
- Calibration verification package

Reviewed By: _____

Date: _____

Approved By: _____

Date: _____

GAMMA SPECTROSCOPY
ISOCS CALIBRATION

Detector ID: _____

Calibration File Names: _____

Modeling Date: _____

CHECK LIST

All Calibration Packages shall include the following items:

- ISOCS Report
- Efficiency Calibration Reports and Graphs
- Sample Information and Sketch

Sample Matrix: _____

Degree of Fullness: _____

Description of Contents: _____

Sketch of Geometry:

Modeled By: _____

Date: _____

Reviewed By: _____

Date: _____

Fly-Away Laboratory Balance Calibration/Adjustment Log

Type: Sartorius CPA6002P

Serial Number: _____

Reference Standard: Internal

Date	Time	Initial Conditions Verification ¹ <input checked="" type="checkbox"/>	Calibration/Adjustment Completed Satisfactorily <input checked="" type="checkbox"/>	Comments	Operator Initial
		<input type="checkbox"/>	<input type="checkbox"/>		
		<input type="checkbox"/>	<input type="checkbox"/>		
		<input type="checkbox"/>	<input type="checkbox"/>		
		<input type="checkbox"/>	<input type="checkbox"/>		
		<input type="checkbox"/>	<input type="checkbox"/>		
		<input type="checkbox"/>	<input type="checkbox"/>		
		<input type="checkbox"/>	<input type="checkbox"/>		
		<input type="checkbox"/>	<input type="checkbox"/>		
		<input type="checkbox"/>	<input type="checkbox"/>		

¹ Procedure 10.2.7 Calibration/Adjustment, Item 3

Fly-Away Laboratory Balance Daily Linearity and Accuracy Check Log

Type: Sartorius PT3100

Serial Number: 70407399

Date: _____

Linearity Check

Range [g]	Weight "A" #'s	Weight "B" #'s	0%-50% [g]	50%-100% [g]	Difference [g]	Range Linearity Tolerance	Completed Satisfactorily <input checked="" type="checkbox"/>	Operator Initial
0-3,100	500 g _____ 1,000 g _____	500 g _____ 1,000 g _____				±0.2	<input type="checkbox"/>	

Accuracy Checks

Weighing Processes (with process tolerance):

100 g (±0.1 g)	200 g (±0.2 g)	500 g (±0.5 g)	1,000 g (±1 g)	3,000 g (±3 g)
----------------	----------------	----------------	----------------	----------------

Process Weight [g]	Weight #	Calibrated Weight (1) [g]	Weight #	Calibrated Weight (2) [g]	Total Weight (1+2) [g]	Measured Weight [g]	Difference [g]	Tolerance [g]	Completed Satisfactorily <input checked="" type="checkbox"/>	Operator Initial
									<input type="checkbox"/>	
									<input type="checkbox"/>	
									<input type="checkbox"/>	
									<input type="checkbox"/>	
									<input type="checkbox"/>	

Comments: _____

Fly-Away Laboratory Balance Daily Linearity and Accuracy Check Log

Type: Sartorius CPA1003P

Serial Number: _____

Date: _____

Linearity Check

Range [g]	Weight "A" #s	Weight "B" #s	0%-50% [g]	50%-100% [g]	Difference [g]	Range Linearity Tolerance	Completed Satisfactorily <input checked="" type="checkbox"/>	Operator Initial
0-500	200 g _____	200 g _____				±0.002	<input type="checkbox"/>	
500-1,010	200 g _____ 500 g _____	200 g _____ 500 g _____				±0.02	<input type="checkbox"/>	

Accuracy Checks

Weighing Processes (with process tolerance):

100 g (±0.1 g)	200 g (±0.2 g)	300 g (±0.3 g)	500 g (±0.5 g)	1,000 g (±1 g)
----------------	----------------	----------------	----------------	----------------

Process Weight [g]	Weight #	Calibrated Weight (1) [g]	Weight #	Calibrated Weight (2) [g]	Total Weight (1+2) [g]	Measured Weight [g]	Difference [g]	Tolerance [g]	Completed Satisfactorily <input checked="" type="checkbox"/>	Operator Initial
									<input type="checkbox"/>	
									<input type="checkbox"/>	
									<input type="checkbox"/>	
									<input type="checkbox"/>	
									<input type="checkbox"/>	

Comments: _____

Fly-Away Laboratory Balance Daily Linearity and Accuracy Check Log

Type: Sartorius CPA6002P

Serial Number: _____

Date: _____

Linearity Check

Range [g]	Weight "A" #'s	Weight "B" #'s	0%-50% [g]	50%-100% [g]	Difference [g]	Range Linearity Tolerance	Completed Satisfactorily <input checked="" type="checkbox"/>	Operator Initial
0-3,000	500 g _____ 1,000 g _____	500 g _____ 1,000 g _____				±0.02	<input type="checkbox"/>	
3,000-6,200	2,000 g _____ 2,000 g _____	2,000 g _____ 2,000 g _____				±0.05	<input type="checkbox"/>	

Accuracy Checks

Weighing Processes (with process tolerance):

100 g (±0.1 g)	500 g (±0.5 g)	1,000 g (±1 g)	2,000 g (±2 g)	4,000 g (±4 g)
----------------	----------------	----------------	----------------	----------------

Process Weight [g]	Weight #	Calibrated Weight (1) [g]	Weight #	Calibrated Weight (2) [g]	Total Weight (1+2) [g]	Measured Weight [g]	Difference [g]	Tolerance [g]	Completed Satisfactorily <input checked="" type="checkbox"/>	Operator Initial
									<input type="checkbox"/>	
									<input type="checkbox"/>	
									<input type="checkbox"/>	
									<input type="checkbox"/>	
									<input type="checkbox"/>	

Comments: _____

Fly-Away Laboratory Balance Weekly Reproducibility Check Log

Balance: Sartorius PT1300

Serial Number: 70407399

Date: _____

SD Tolerance: ≤ 0.1 g

Range [g]	Weight # & Calibrated Mass	#	Full Scale Reading [g]	Zero Reading [g]		Range [g]	Weight # & Calibrated Value	#	Full Scale Reading [g]	Zero Reading [g]	Comments	Operator Initial
0-3,100	1 kg	1				n/a	n/a	1	n/a	n/a		
	#: _____	2						2	n/a	n/a		
		3						3	n/a	n/a		
	c.m.: _____ ± _____	4						4	n/a	n/a		
	2 kg	5						5	n/a	n/a		
	#: _____	6						6	n/a	n/a		
		7						7	n/a	n/a		
	c.m.: _____ ± _____	8						8	n/a	n/a		
		9						9	n/a	n/a		
		10						10	n/a	n/a		
CV	Total Calibrated Mass		SD	SD		CV	Total Calibrated Mass		SD	SD	SD < SD Range Tolerance <input checked="" type="checkbox"/>	
	_____ ± _____					n/a	n/a		n/a	n/a	<input type="checkbox"/>	

1. Enter data for weights and measurements for each range.
2. Transcribe values to Reproducibility Spreadsheet (spreadsheet calculates standard deviations (SD) & coefficients of variation (CV)).
3. Transcribe SD & CV values from spreadsheet to log as indicated.
4. If SD values are less than the tolerance SD for each range, the reproducibility check is satisfactory.

Fly-Away Laboratory Balance Weekly Reproducibility Check Log

Balance: Sartorius CPA1003P

Serial Number: _____

Date: _____

0-500 g Range SD Tolerance: ≤ 0.001 g

500-1,010 g Range SD Tolerance: ≤ 0.01 g

Range [g]	Weight # & Calibrated Mass	#	Full Scale Reading [g]	Zero Reading [g]		Range [g]	Weight # & Calibrated Value	#	Full Scale Reading [g]	Zero Reading [g]	Comments	Operator Initial
0-500	500 g	1				500-1,010	1 kg	1				
	#: _____	2					#: _____	2				
		3						3				
	c.m.: _____ ± _____	4					c.m.: _____ ± _____	4				
		5						5				
		6						6				
		7						7				
		8						8				
		9						9				
		10						10				
CV	Total Calibrated Mass		SD	SD		CV	Total Calibrated Mass		SD	SD	SD < SD Range Tolerance <input checked="" type="checkbox"/>	
	± _____					± _____					<input type="checkbox"/>	

1. Enter data for weights and measurements for each range.
2. Transcribe values to Reproducibility Spreadsheet (spreadsheet calculates standard deviations (SD) & coefficients of variation (CV)).
3. Transcribe SD & CV values from spreadsheet to log as indicated.
4. If SD values are less than the tolerance SD for each range, the reproducibility check is satisfactory.

Fly-Away Laboratory Balance Weekly Reproducibility Check Log

Balance: Sartorius CPA6002P

Serial Number: _____

Date: _____

0-3,000 g Range SD Tolerance: ≤ 0.01 g

3,000-6,200 g Range SD Tolerance: ≤ 0.03 g

Range [g]	Weight # & Calibrated Mass	#	Full Scale Reading [g]	Zero Reading [g]		Range [g]	Weight # & Calibrated Value	#	Full Scale Reading [g]	Zero Reading [g]	Comments	Operator Initial
0-3,000	1 kg	1				3,000-6,200	2 kg	1				
	#: _____	2					#: _____	2				
		3						3				
	c.m.: _____ ± _____	4					c.m.: _____ ± _____	4				
	2 kg	5					2 kg	5				
	#: _____	6					#: _____	6				
		7						7				
	c.m.: _____ ± _____	8					c.m.: _____ ± _____	8				
		9					2 kg	9				
		10					#: _____	10				
						c.m.: _____ ± _____						
CV	Total Calibrated Mass		SD	SD		CV	Total Calibrated Mass		SD	SD	SD < SD Range Tolerance <input checked="" type="checkbox"/>	
	_____ ± _____					_____ ± _____					<input type="checkbox"/>	

1. Enter data for weights and measurements for each range.
2. Transcribe values to Reproducibility Spreadsheet (spreadsheet calculates standard deviations (SD) & coefficients of variation (CV)).
3. Transcribe SD & CV values from spreadsheet to log as indicated.
4. If SD values are less than the tolerance SD for each range, the reproducibility check is satisfactory.

Appendix C: Interferences and Limitations

Limitations for AIR FILTERS ONLY

To determine if there is alpha activity (excluding Radon and Thoron daughters) on an air filter soon after it has been removed from the air flow, the filter needs to be counted for 2 minutes to determine the gross level of activity. It then needs to be recounted for 10 minutes to more accurately determine the activity.

The background subtract algorithm does not always give a result of 'zero' dpm if there is no activity on the filter.

The algorithm was tested by sampling with two filters overnight in a clean room and reading the filters in the morning. The test was repeated 5 times. Results are shown below. Note that the 2-minute count results varied from -120 to +10 dpm. Therefore, given the algorithm subtracts 120 dpm as background, it would be possible to have 120 dpm of Pu on the filter and have the result indicate '0 dpm.' Longer count times lessen the likelihood of not reporting 'real' activity.

Table 7.1: Estimated Background Rates

Length of count following a 1 to 3 day sampling interval	Bkgd results for 'clean' air (dpm)
2 min	-120 to +10
10 min	-50 to +40
30 min	-15 to +5
60 min	-1 to +10

NOTE: 5 dpm represents 0.6 DAC-hr of Class W ^{239}Pu and 0.2 DAC-hr of Class Y ^{239}Pu (assuming air flow sampling rate of 30 lpm)